

1. NO GUN EXAMINATION REPORT NUMBER: _____ MODEL: 700 EPL
 GENERAL CONDITION: NEW R #: 006000
 OUTSIDE WORK: SAFETY WORK DATE: 3-13-72
 FIRED AMMO TYPE: _____ FROM: BRASS, HORN CO.
 & CONDITION: _____ BREVETED, P.P.
 PROOF: R.E.P. INSP.: 79 TEST: 87 GUN #: 6245354
 HEADING: _____ CODE: 05-2/65
 BREACH OPENING: _____ GR./CAL.: 308
 RECOIL SHOULDERS: O.K. CHECKED BY: C.P. 4/4/72
 CHAMBER: O.K. APPROVED: _____
 TEST: NO APPROVED: _____
 COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: _____

SEALING INJECT. ENTIRELY NEW (P. 100) (P. 100)
 CONNECTOR AS SHOWN IN FIG. 1069 (P. 100) TRIGGER
 CLEARANCE ON CONNECTOR = 1.090 (P. 100) THIS ADDS UP TO
 .014 MORE CLEARANCE BETWEEN CONNECTOR AND TRIGGER THAN
 SPECIFICATIONS.

COMPLAINT: FIRING WHEN SAFETY IS RELEASED

INCIDENT: FOLLOW DOWN

COMMENTS: THE EXCESSIVE CLEARANCE
AND CONNECTOR ALIGNMENT
WAS CAUSE OF THE SEVERE FIRE
CAUSING FOLLOW DOWN.

PLAINTIFF'S
EXHIBIT

3236

AL 0029768