If I have a remington $660\ with a$ "V" stamped on the trigger under the recieve...

Discussion Thread

Response (Jessica) Dear Mark, 11/27/2002 9:26:50 AM

Thank you for your inquiry. The "V" does indicate that the trigger assembly was replaced under the recall. Please click on the link below for further information:

http://www.remington.com/Safety_Modification_Program/600_660.htm

Customer (Mark Donchek) 11/26/2002 9:48:26 AM If I have a remington 660 with a "V" stamped on the trigger under the reciever then does this mean that I DO NOT need any repairs regarding the 1979 recall of this model? Thank you.

