

In cold weather (20 degrees or colder) the rifle misfires. The firing pin  
sea...

Discussion Thread

Response (Dell)

12/23/2002 3:35:22 PM

Dear Jim,

The following link will provide you with information on our Model 700  
Safety Modification Program.

[http://www.remington.com/Safety\\_Modification\\_Program/remington\\_safety.htm](http://www.remington.com/Safety_Modification_Program/remington_safety.htm)

Customer (Jim Murtha)

12/10/2002 7:19:25 PM

> Remington Representative,

>

> Thank you for your response.

>

> I am more then a little surprised by the response. As a 30 plus year  
owner

> I

> have not previously heard of any manufacturer recommending yearly

> professional cleaning of the bolt from either sales, trade show

> representatives or other enthusiasts. I have had the bolt cleaned at a

> cost

> of \$40.00 by a local gunsmith. I think this type of routine maintenance

> should be able to be completed by the owner.

>

> I have a second question.

> I recently heard there is a recall on older Model 700's. Can you provide

> the

> details?

>

> Thank you

>

> Jim

>

>