

My first rifle as a youth was a Mohawk 600 in 6mm Remington caliber. I have a...

Discussion Thread

Response (Chris)

2/4/2003 12:11:54 PM

Dear Mr. Lanager,

Thank you for contacting Remington Country. Certain Model 600 firearms were recalled to replace the trigger. To check your serial number and for additional safety information on this model, go to:  
[http://www.remington.com/Safety\\_Modification\\_Program/remington\\_safety.htm](http://www.remington.com/Safety_Modification_Program/remington_safety.htm)

Customer (Cyrus Lanager)

2/2/2003 4:40:06 PM

My first rifle as a youth was a Mohawk 600 in 6mm Remington caliber. I have always enjoyed the gun, and would like to give it to my son when he is old enough. I heard that the Mohawk 600 was recalled because of some safety problems. Is this true, and how could I get my gun repaired?