

I have a model 600 short bolt.(223) I don't have the model # and serial # on ...

Discussion Thread

Response (Chris)

7/9/2003 12:46:46 PM

Dear Mr. Peterson,

Thank you for contacting Remington Country. If the Model 600 was produced before 1975 and does not have a "V" stamped on the trigger, we suggest taking or sending your firearm to a Remington Authorized Repair Center or our factory for evaluation.

You can locate your nearest repair center by visiting the Repair Information Center in our Support Section and selecting your model and state:

<http://www.remington.com/repairsvc/Modelselection.asp>

To view more information on this safety message, go to:

http://www.remington.com/safety_modification_program/remington_safety.htm

Customer (Mark Peterson)

7/7/2003 8:13:26 PM

I have a model 600 short bolt.(223) I don't have the model # and serial # on me at the time of Email. I do not think it has been repaired for the problem with the bolt. Do you still do these? How much? Send it where?

Mark Peterson