

I PURCHASED A MODEL 600 .243 RIFLE NEW IN 1967. FOR MANY YEARS I HAVE HAD  
A P...

Discussion Thread

Response (Chris)

7/15/2003 2:00:57 PM

Dear Len,

Thank you for contacting Remington Country. Your Model 600 was produced in 1967 and should be inspected for a trigger recall. We suggest taking or sending your firearm to a Remington Authorized Repair Center or our factory for evaluation.

You can locate your nearest repair center by visiting the Repair Information Center in our Support Section and selecting your model and state:

<http://www.remington.com/repairsvc/Modelselection.asp>

To view more information on this safety message, go to:

[http://www.remington.com/safety\\_modification\\_program/remington\\_safety.htm](http://www.remington.com/safety_modification_program/remington_safety.htm)

Customer (LENNY LOWE)

7/15/2003 8:10:44 AM

I PURCHASED A MODEL 600 .243 RIFLE NEW IN 1967. FOR MANY YEARS I HAVE HAD A PROBLEM WITH THE FUNCTION OF THE SAFETY. I LEARNED HOW TO LIVE WITH THE PROBLEM, HOWEVER, NOW THAT I WILL BE PASSING THE GUN ON TO MY SON, I WANT TO GET IT REPAIRED TO PREVENT A SERIOUS PROBLEM FOR HIM. CAN YOU TELL ME WHAT I NEED TO DO TO GET THE SAFETY TO FUNCTION PROPERLY? WILL A GUNSMITH NEED TO DO THE REPAIR? THANK YOU FOR YOUR CONSIDERATION OF MY PROBLEM.  
LEN