

P NO GUN EXAMINATION REPORT NUMBER: _____ MODEL: 700 ADL
 GENERAL CONDITION: GOOD R #: 005856
 OUTSIDE WORK: NO DATE: 3-7-72
 FIRED AMMO TYPE: _____ FROM: CONRAD SGT. ADS.
 & CONDITION: _____ MOBERLY, MO.
 PROOF: R.E.P.-E INSP.: 9 TEST: 13 GUN #: 6243-00
 HEADING: _____ CODE: 05-6/69
 BREECH OPENING: _____ GA./CAL.: 309
 RECOIL SHOULDERS: OK CHECKED BY: C. PROSSER
 CHAMBER: OK APPROVED: _____
 TEST: 12 APPROVED: _____
 COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: _____

NO DAMAGED, BROKEN COMPONENTS. TRIGGER PULL 8 LBS.

NO TRIGGER-TRIGGER GUARD INTERFERENCE. REAR-LOCK
ECTOR ENGAGEMENT = .020 (MIN. IS .020) SPRING 14-22.
HEAVILY OILED.

COMPLAINT: "GUN SOMEHOWS WILL FIRE AT 300 YD. BOW IS
ENGAGED WITH THE TRIGGER BOW."

INCIDENT: FOLLOWING DOWN

COMMENTS: IT APPEARS DEFECTS BEING FOUND TO THE

OIL USED PROBABLY CAUSED THE TRIGGER TO
BEHAVE AS IF IT WOULD FIRE BY PRESSING THE FOLLOWING
DOWN MALFUNCTION.

PLAINTIFF'S
EXHIBIT

3240

1 of 1

AL 0029772