

Model 660 recall

Discussion Thread

Response (Chris)

12/5/2003 4:56:30 PM

Dear Mr. Lilley,

Thank you for contacting Remington Country. If you do not see a "V" stamped on the trigger, we suggest taking or sending your firearm to a Remington Authorized Repair Center or our factory for evaluation. If you will forward the serial number, we can check to see if your rifle was included in the recall.

You can locate your nearest repair center by visiting the Repair Information Center in our Support Section and selecting your model and state:

<http://www.remington.com/repairsvc/Modelselection.asp>

To view more information on this safety message, go to:

[http://www.remington.com/safety\\_modification\\_program/remington\\_safety.htm](http://www.remington.com/safety_modification_program/remington_safety.htm)

Customer (Randy Lilley)

12/3/2003 11:52:55 AM

Hi, I just found out there was a recall for my model 660. ... "In 1979, Remington instituted a recall for model 600 and 660 rifles made before February, 1975, because, under certain circumstances, the safety and trigger could be manipulated in a way that could result in an accidental discharge. Under the 1979 recall program, owners of the affected rifles could return their guns for installation of a new trigger assembly at no charge. Since 1979, thousands of the affected firearms have been serviced under the 1979 recall and received new trigger assemblies."

I realize I am a little late, but can I still get my 660 fixed?  
Thanks, Randy