

Paducah, KY 42001
Phone: 270-442-3242
Fax: 270-442-5022

Send to Williams Gun Sight if you live in the following states: MI, NY,
CT, RI, NJ, MA, ME
Williams Gun Sight & Outfitters
7389 Lapeer Rd., Route #1
P.O. Box 329
Davidson, MI 48423
Phone: 810-653-2131
Fax: 810-658-2140

You can find additional Remington warranty centers for the US and
internationally at the following section of our site.

<http://www.remington.com/repairsvc/modelselection.asp>

To view the warranty for Remington firearms, go to:

<http://www.remington.com/support/warranty.htm>

Customer (Rick Sharpe) 12/26/2003 11:29:36 PM
I have a model 700 ADL that I purchased new in 1974. I also purchased a
700 BDL in the late 1990's. My old 700 must have the safety in the fire
position to pull the bolt back while the newer model will allow you to
pull the bolt back to eject the bullets in the safety position. Is it
possible to modify the older 700 to allow the bolt to come back in the
safety position? Otherwise, the gun has performed flawlessly for the past
30 years.

Thank you,