

model 600

Discussion Thread

Response (Chris)

1/8/2004 3:33:50 PM

Dear Mr. Whitworth,

Thank you for contacting Remington Country. Your Model 660 was produced in 1968 and should be inspected for a trigger recall. We suggest taking or sending your firearm to a Remington Authorized Repair Center or our factory for evaluation.

You can locate your nearest repair center by visiting the Repair Information Center in our Support Section and selecting your model and state:

<http://www.remington.com/repairsvc/Modelselection.asp>

To view more information on this safety message, go to:

[http://www.remington.com/Safety\\_Modification\\_Program/remington\\_safety.htm](http://www.remington.com/Safety_Modification_Program/remington_safety.htm)

Customer (kendell whitworth)

1/6/2004 9:14:09 AM

i have a model 600 .308 cal.

i have been told there is a defect in the safety mechanism that may fire being on safety. can you give some information as to what the exact problem may be.