

Mohawk 600 Trigger Repair

Discussion Thread

Response (Chris)

2/10/2004 4:10:45 PM

Dear Mr. Klimple,

Thank you for contacting Remington Country. Your Model 600 was produced in 1968 and should be inspected for a trigger recall. We suggest taking or sending your firearm to a Remington Authorized Repair Center or our factory for evaluation. If it has already been inspected it would have a "V" stamped on the trigger.

You can locate your nearest repair center by visiting the Repair Information Center in our Support Section and selecting your model and state:

<http://www.remington.com/repairsvc/Modelselection.asp>

To view more information on this safety message, go to:

http://www.remington.com/safety_modification_program/remington_safety.htm

Customer (Bob Klimple)

2/5/2004 8:42:55 PM

I had the barrel replaced on my Remington Mohawk 600. The gunsmith told me that the safety/trigger assembly was a recall item.