

I. NA GUN EXAMINATION REPORT NUMBER: _____ MODEL: 700
 GENERAL CONDITION: GOOD R #: 22234
 OUTSIDE WORK: TRIGGER SCREWS READJUSTED DATE: 12/2/67
 FIRED AMMO TYPE: UNKNOWN FROM: WESLER WEITER
 & CONDITION: _____ ARMS ETC
205 SECOND ST
SAN FRANCISCO CAL
 GUN #: 300523
 PROOF: REP INSP.: 14 TEST: 58 8-67
 HEADING: OK 20 WIN
 BREACH OPENING: _____ CHECKED BY: MT
 RECOIL SHOULDERS: NORMAL APPROVED: [Signature]
 CHAMBER: _____ APPROVED: [Signature] 1/3/68
 TEST: _____ APPROVED: _____
 COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: _____

STOCK CRACKED, BUTT PLATE MISSING, MAGAZINE
BOX DEFORMED

GUN FIRED WHEN SAFE WAS MOVED TO
POSITION (PER CUSTOMER)

INCIDENT: GUN APPARENTLY FIRED WHEN SAFE WAS RELEASED AND
TRIGGER INADVERTENTLY PULLED AT SAME TIME OR GUN WAS
HIT CAUSING JAR OFF DUE TO IMPROPER SETTING.

COMMENTS: SEAL WAS REMOVED FROM TRIG. ADJUSTING SCREW AND EN-
GAGEMENT SET LESS THAN RECOMMENDED. 620 MIN. ENGAGEMENT
SCREW ALSO SHOWS EVIDENCE OF HAVING BEEN MOVED
TRIGGER PULL WAS CHANGED SO THAT [REDACTED] APPROXIMATE
1 1/2 LBS. EVEN SO WAS NOT ABLE TO [REDACTED] FOLLOW-
DOWN AT PRESENT SETTING AS CUSTOMER MAINTAINS.

PLAINTIFF'S
 EXHIBIT

3242

AL 0029774

1 of 1