

Model 600

Discussion Thread

Response (Chris)

1/13/2005 11:34:41 AM

Dear Jack,

Thank you for your patience. Your Model 600 was produced in 1966 and should be inspected for a trigger recall. We suggest taking or sending your firearm to a Remington Authorized Repair Center or our factory for evaluation.

You can locate your nearest repair center by visiting the Repair Information Center in our Support Section and selecting your model and state:

<http://www.remington.com/repairsvc/Modelselection.asp>

To view more information on this safety message, go to:

http://www.remington.com/Safety_Modification_Program/remington_safety.htm

We no longer house any parts for this model. For your convenience we have included a link below to a list of establishments that may offer parts or services for your older Remington firearm.

<http://www.remington.com/support/parts/obsolete.htm>

Additional information regarding parts and service can be found in our Support Section under "Obtaining Services".

Remington does not offer repair or reconditioning on discontinued models, however the following Remington Repair Center specializes in reconditioning and offers a machine shop. He may offer the work you are requesting.

Craig Colabaugh Gunsmith, Inc.
R.D. 4 Box 4168- Gumm Street
Stroudsburg, PA 18360
Phone: 570-992-4499

Customer (Jack Rathgeber)

1/4/2005 10:05:01 AM

Dear Remington:

Thanks for your response - my issue is now resolved. I spoke to Craig and he is very helpful.

Continued success, Jack