

Bolt Lock System

Discussion Thread

Response (Chris)

2/7/2005 9:37:24 AM

Dear Mr. Owen,

Thank you for your patience. There has been no failures in the field but a service center can change the firing pin assembly for a small fee.

You can find your nearest Remington Authorized Repair Center at the following section of our site.

<http://www.remington.com/repairsvc/modelselection.asp>

Customer (Greg Owen)

2/2/2005 5:36:36 PM

I have three model 700 rifles. 300um, 338um and 30-06. All have the J lock on the bolt. I have heard that this system is being discontinued due to failure problems in the field. If true, can this system be removed from my rifles by a factory service center.