

Model 600

Discussion Thread

Response (Chris)  
Dear Mr. Squires,

3/10/2005 10:42:28 AM

Thank you for contacting Remington Country. Your Model 600 was produced in 1967 and should be inspected for a trigger recall. If it had already been updated it would have a "V" stamped on the trigger.

We suggest taking or sending your firearm to a Remington Authorized Repair Center or our factory for evaluation.

You can locate your nearest repair center by visiting the Repair Information Center in our Support Section and selecting your model and state:

<http://www.remington.com/repairsvc/ModelSelection.asp>

To view more information on this safety message, go to:

[http://www.remington.com/Safety\\_Modification\\_Program/remington\\_safety.htm](http://www.remington.com/Safety_Modification_Program/remington_safety.htm)

Customer (Rick Squires)

3/9/2005 10:48:01 PM

I have a model 600 in .308 caliber with a s/n of 86001. can you tell me if your organization has performed all of the necessary recall work for this firearm.

Thanks