

NOT A BLOW-UP

1. NO GUN EXAMINATION REPORT NUMBER: _____ MODEL: 700
 GENERAL CONDITION: NEW R #: 1514
 OUTSIDE WORK: TRIGGER PULL ADJUSTED. DATE: 1-22-70
 FIRED AMMO TYPE: — FROM: DENVER,
— COLORADO
 & CONDITION: _____ GUN #: 6227025
 PROOP: R.E.F. INSP.: 73 TEST: _____ = 3/69
 HEADING: — _____ 250
 BREACH OPENING: — CHECKED BY: E. PROSSER
 RECOIL SHOULDERS: O.K. APPROVED: _____
 CHAMBER: O.K. APPROVED: _____
 TEST: DRY FIRED - MALFUNCTION VERIFIED. APPROVED: _____
 COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: _____

FIRES WHEN RELEASING SAFETY TO OFF POSITION.

INCIDENT: SAFETY DOES NOT LIFT SEAR CLEAR OF TRIGGER
CONNECTOR.

COMMENTS: SAFETY, HOUSING, TRIGGER CONNECTOR & TRIGGER
WERE MEASURED. ONLY THE TRIGGER WAS FOUND TO
BE NOT TO SPECIFICATIONS. DIMENSIONS FROM 1 OF 2.
HOLE TO TOP BEING .9782 (MODE - DRAWING = .971)

PLAINTIFF'S
EXHIBIT

3243

AL 0029775