

remington mohawk 600(308 cal.)

Discussion Thread

Response (Chris)

10/4/2005 9:30:13 AM

Dear Mr. Felt,

Thank you for contacting Remington Country. Your Model 600 was produced in 1975 and should be inspected for a trigger recall if you do not see a "v" stamped on the trigger. The "v" signifies we have already inspected it for the trigger recall.

We suggest taking or sending your firearm to a Remington Authorized Repair Center or our factory for evaluation.

You can locate your nearest repair center by visiting the Repair Information Center in our Support Section and selecting your model and state:

<http://www.remington.com/repairsvc/Modelselection.asp>

To view more information on this safety message, go to:

http://www.remington.com/Safety_Modification_Program/remington_safety.htm

customer (frederick felt)

10/3/2005 5:30:53 PM

Bought this rifle from a friend. Today i found out this gun was part of a big recal in the 60 s .reason had to do with the safety not being reliable, and unsafe discharge of this rifle. I would like to know ,if possible you can check if this on was fixed. the number is 6846590. I like the gun. I would hate to put it away and not use it for it being unsafe to use. thank you . Frederick t. Felt.