

NO GUN EXAMINATION REPORT NUMBER: _____ MODEL: 700 BDL
 GENERAL CONDITION: NEW R #: 22570
 OUTSIDE WORK: NO DATE: 11-2-70
 FROM: LIMA, OHIO
 FIRED AMMO TYPE: _____
 & CONDITION: _____ GUN #: 6233914
 PROOF: _____ INSP.: _____ TEST: _____ CODE: CS = 4/69
 HEADING: _____ GA./CAL.: 222
 BREECH OPENING: _____ CHECKED BY: C. PROSSER
 RECOIL SHOULDERS: _____ APPROVED: _____
 CHAMBER: _____ APPROVED: _____
 TEST: NO APPROVED: _____
 COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: _____
O.K.

COMPLAINT: FIRES WHEN SAFE IS RELEASED.

INCIDENT: TRIGGER CONNECTOR MOVES UP WHEN TRIGGER IS PULLED WITH THE SAFETY ON.

COMMENTS: TRIGGER CONNECTOR IS .007 OVERSIZE ON TRIGGER CLEARANCE. TRIGGER IS .006 UNDERSIZE ON CONNECTOR CLEARANCE. THIS EXCESSIVE CLEARANCE ALLOWS THE CONNECTOR TO WORK UP, INTERFERES WITH THE SEAR AND FAIL TO RETRACT UNDER THE SEAR RESULTING IN FOLLOW DOWN WHEN THE SAFETY IS PUSHED OFF.

PLAINTIFF'S
EXHIBIT

3244

10 of 1
AL 0029776