

Model 700ADL

Discussion Thread

Response (Jesse)

12/7/2005 5:24:26 PM

Dear August,

Thank you for visiting Remington Country! We certainly appreciate you taking the time to write in with your question. This sounds like a model 700 made before 1982. There is a safety modification program for rifles such as this one. See on our website:  
[http://www.remington.com/safety/safety\\_center/safety\\_modification\\_program/](http://www.remington.com/safety/safety_center/safety_modification_program/)

Should you have additional questions, please feel free to contact our Consumer Services Department at 800-243-9700, 9:00 am - 5:00 pm, EST, Monday through Friday.

Customer (August Olivier)

12/2/2005 1:45:14 PM

I recently purchased a used model 700ADL (30-06). In order to unload it I must cycle cartridges thru the chamber. The only way to do this is if the safety is in the "off" position. I was told that there may be a rework that can be done by a competent gunsmith and approved by Remington which will allow the bolt to be cycled while the safety is in the "on" position. If this is true can you forward me the information to get this done by a gunsmith.