

never repaired as part of that recall, then a new trigger assembly without a bolt-lock feature will be installed. This change will be made at no cost to you.

• If your Model 600 or 660 rifle was repaired as part of the 1979 recall, or it was not subject to the 1979 recall, you may have the bolt-lock removed at a total cost of \$20, plus tax. You will also receive a rebate coupon good for up to \$20 towards the purchase of any Remington safety product, including gun locks, hearing and eye protection and gun safes.

How to participate in the Safety Modification Program

Complete the General Repair Form and Send or deliver your firearm and the completed repair form to either:

- a) A Remington Authorized Repair Center; or
- b) Ship your firearm to the Remington factory at:
Remington Arms Company, Inc.
Ilion Firearms Plant
Attention: BL Safety Program
14 Hoefler Avenue
Ilion, NY 13357

Remington will bill or arrange for payment once your firearm is received and evaluated.

Feel free to contact us at 1-800-241-9700 M-F 9-5pm EST if additional information is required.

CAUTION: It is your responsibility to comply with all laws and regulations regarding transportation or shipping of your firearm. Absolutely no ammunition should be packaged with the firearm whether loaded in the firearm itself or included in the shipping container. The firearm should be transported only in a completely unloaded condition.

K. Howerton
Consumer Services

Customer (Keith Vick) 12/22/2005 5:22:03 PM
I have a 6MM Remington serial # 72185 Model 600. Can you tell me the date of manufacture? I also heard of a recall on this gun regarding the trigger. How can I tell if this gun has been repaired?