

Customer Complaint

NO GUN EXAMINATION REPORT NUMBER: _____ MODEL: 700

GENERAL CONDITION: NEW R #: 02095

OUTSIDE WORK: SCOPE MOUNTED DATE: 1-24-71

FROM: NAGEL'S GUN SHOP

FIRED AMMO TYPE: _____ SAN ANTONIO, TEXAS.

& CONDITION: _____ GUN #: 6206774

PROOF: R.E.P. INSP.: 9 TEST: 13 CODE: B5-1/69

HEADING: O.K. GA./CAL.: 270 WIN.

BREACH OPENING: - CHECKED BY: C. PROSSER

RECOIL SHOULDERS: O.K. APPROVED: _____

CHAMBER: O.K. APPROVED: _____

TEST: NO APPROVED: _____

COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: _____

COMPLAINT: "FIRES WHEN YOU RELEASE SAFETY"INCIDENT: FOLLOWS DOWN

PLAINTIFF'S
EXHIBIT
3246

COMMENTS: TRIGGER CLEARANCE ON TRIGGER CONNECTOR = 1.091

MODEL DRAWING = 1.080

1.063 OVERSIZE .008; CONNECTOR

CLEARANCE ON TRIGGER = 1.068 MODEL DRAWING = 1.076

UNDERSIZE .008. ALTHOUGH THE MALFUNCTION COULD

NOT BE DUPLICATED, THE EXCESSIVE CLEARANCE BETWEEN

CONNECTOR & TRIGGER WOULD ALLOW INTERFER-

ENCE BETWEEN CONNECTOR & SEAR AND RESULT

IN FOLLOW DOWN.