

Customer Complaint

F... NO GUN EXAMINATION REPORT NUMBER: _____ MODEL: 700 ADLGENERAL CONDITION: NEW R #: 06640OUTSIDE WORK: NO DATE: 3-9-71FIRED AMMO TYPE: _____ FROM: JOE W. HARRISVICTORIA, TEXAS.& CONDITION: _____ GUN #: 6364870PROOF: R.E.P.-A INSP.: D TEST: 13 CODE: WT = 11/70HEADING: O.K. GR./CAL.: 270 WIN.BREECH OPENING: _____ CHECKED BY: C. PROUDERRECOIL SHOULDERS: O.K. APPROVED: _____CHAMBER: O.K. APPROVED: _____TEST: NO APPROVED: _____

COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: _____

NO BROKEN OR DAMAGED COMPONENTSCOMPLAINT: FIRE WHEN SAFETY WAS PUSHED OFF.PLAINTIFF'S
EXHIBIT

3247

INCIDENT: FOLLOWED DOWNCOMMENTS: CONNECTOR-SEAR ENGAGEMENT .010, MIN. IS .015THIS COUPLED WITH A TOO HEAVY LUBRICANT AND SLIGHTLY
ROUNDED SEAR, PROBABLY LED TO THE MALFUNCTION.THE MALFUNCTION COULD NOT, HOWEVER, BE
DUPLICATED HERE.ENGAGEMENT RE-ADJUSTED TO .015.

AL 0029779