

1 NO GUN EXAMINATION REPORT NUMBER: _____MODEL: 700 ADLGENERAL CONDITION: FAIRR #: 11954OUTSIDE WORK: SCOPE MOUNTEDDATE: 6-2-71

FIRED AMMO TYPE: _____

FROM: NATIONAL PK. SYS.
KAHULUI, MAUI, HAWAII

& CONDITION: _____

GUN #: 6258351PROOF: R.E.P.-E. INSP.: U TEST: 87CODE: OS = 7/69HEADING: O.K.GA./CAL.: 300GBREECH OPENING: -CHECKED BY: C. PROSSERRECOIL SHOULDERS: O.K.

APPROVED: _____

CHAMBER: O.K.

APPROVED: _____

TEST: NO

APPROVED: _____

COMPONENT CONDITION: (Damaged, Broken, Old Style)

APPROVED: _____

NO BROKEN ETC. COMPONENTS.CONNECTOR CLEARANCE ON TRIGGER = 1.069 M/D = 1.079 - 1.007TRIGGER CLEARANCE ON CONNECTOR = 1.089 M/D = 1.088 - 1.006CONNECTOR - SEAR ENGAGEMENT = 0.015 (0.005 UNDER MIN.)TRIGGER PULL FIVE POUNDS. EXCESSIVE LUBRICANTS?COMPLAINT: FIRES WHEN SAFETY IS PUSHED OFF.PLAINTIFF'S
EXHIBIT

3248

INCIDENT: TRIGGER CONNECTOR FAILED TO RETRACTCOMMENTS: CAN NOT DUPLICATE CUSTOMER'S MALFUNCTION.THE TRIGGER-CONNECTOR & TRIGGER NOT TO MODELDRAWING PERMIT SEAR, CONNECTOR INTERFERENCEFAILURE TO RETRACT.