

Customer Complaint

NO GUN EXAMINATION REPORT NUMBER: _____ MODEL: 700 ADL
 GENERAL CONDITION: FAIR R #: 12933
 OUTSIDE WORK: SCOPE MOUNTED DATE: 6-23-71
 FIRED AMMO TYPE: _____ FROM: NAT. PARK SERV.
 & CONDITION: _____ KAHULUI, MAUI, HAWAII
 PROOF: R.E.P.-E INSP.: 11 TEST: 87 GUN #: 6258663
 HEADING: O.K. CODE: 05-7/69
 BREACH OPENING: - G.K./CAL.: 3006
 RECOIL SHOULDERS: O.K. CHECKED BY: C. PROSSER
 CHAMBER: O.K. APPROVED: _____
 TEST: NO APPROVED: _____
 COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: _____

NO BROKEN COMPONENTS

CONNECTOR CLEARANCE ON TRIGGER 1.062 M/D = ^{1.079}_{1.072} ±.014
 TRIGGER CLEARANCE ON CONNECTOR 1.087 M/D = ^{1.033}_{1.020} ±.004
 CONNECTOR-SEAR ENGAGEMENT .025-O.K.

COMPLAINT: FIRES WHEN SAFETY IS PUSHED OFF.

INCIDENT: TRIGGER CONNECTOR FAILED TO RETRACT.

COMMENTS: CAN NOT DUPLICATE THE CUSTOMER'S MALFUNCTION.
THE TRIGGER CONNECTOR & TRIGGER NOT TO MODEL
DRAWING PERMIT SEAR, CONNECTOR INTERFERENCE,
FAILURE TO RETRACT.

PLAINTIFF'S
EXHIBIT

3250

1 of 1

AL 0029782