

Customer Complaint

NO GUN EXAMINATION REPORT NUMBER: _____

MODEL: 700 ADL

GENERAL CONDITION: USED

R #: 22448

OUTSIDE WORK: SCOPE MOUNTED

DATE: 11-8-71

FIRED AMMO TYPE: _____

FROM: THE SPORTSMAN

HARLINGEN, TEXAS

& CONDITION: _____

GUN #: 276664

PROOF: R.E.P. INSP.: 9 TEST: 87

CODE: RP. 5/67, OTS: 7/70

HEADLUG: _____

CHK./CHK.: _____

BREECH OPENING: _____

CHECKED BY: C. PROSSER

RECOIL SHOULDERS: O.K.

APPROVED: _____

CHAMBER: O.K.

APPROVED: _____

TEST: NO

APPROVED: _____

COMPONENT CONDITION: (Damaged, Broken, Old Style)

APPROVED: _____

NO DAMAGED, OR BROKEN COMPONENTS

TRIGGER BINDS ON GUARD. TRIGGER PULL $2\frac{1}{2}$ POUNDS.

COMPLAINT: "FIRES WHEN SAFETY IS PUT IN FIRE POSITION"

INCIDENT: FOLLOWS DOWN

COMMENTS: WITH THE TRIGGER PULL LIGHT ($2\frac{1}{2}$ POUNDS) AND THE TRIGGER BINDING ON THE GUARD, IT IS POSSIBLE THAT TRIGGER COMPRESSOR RETRACTION WOULD BE SUFFICIENT. THIS COULD CAUSE FOLLOW ON DOWN WHEN THE TRIGGER IS PULLED WITH THE SAFETY ON.

PLAINTIFF'S
EXHIBIT

3252

AL 0029784

1 of 1