

F NO GUN EXAMINATION REPORT NUMBER: _____GENERAL CONDITION: GOODOUTSIDE WORK: NO

FIRED AMMO TYPE: _____

& CONDITION: _____

PROOF: R.E.A.-A INSP.: J TEST: 87HEADING: OKBREECH OPENING: -RECOIL SHOULDERS: OKCHAMBER: OKTEST: NO

COMPONENT CONDITION: (Damaged, Broken, Old Style)

NO BROKEN OR DAMAGED COMPONENTS.TRIGGER CONNECTED 1001 (MID-1935) TRIGGER 1062 (MID-1935)CONNECTED - SEAR ENGAGEMENT 030 MID 1915, TRIGGERPULL: 4 TO 4 1/2 LBS. LUBRICANT USED APPLIED TO 35 TUBHEAVY.COMPLAINT: WHEN PUSHING SAFETY OFF THE GUN FIRES OFF.INCIDENT: FALLING DOWN.Carab ComplaintMODEL: 700 AGLR # : 23155DATE: 11-18-71FROM: BIGGS SGT. GUN.PENSACOLA, FLA.GUN # : 6344022CODE: KT-5/10GA./CAL.: 22-250CHECKED BY: G.F. GUN.

APPROVED: _____

APPROVED: _____

APPROVED: _____

APPROVED: _____

PLAINTIFF'S
EXHIBIT

3254

COMMENTS: WITH THE EXCESSIVE GREASE BETWEEN THETRIGGER AND THE TRIGGER SPRING LEVER.THE TRIGGER SPRING LEVER WAS DISCONNECTED UP UNTILIT CLIPPED ON THE TRIGGER SPRING LEVER.IN THE MEANWHILE THE TRIGGER SPRING LEVER WASBEING THE FORCE WAS PUSHED TO THE TRIGGER SPRING LEVER.

(1 of 1)