(Model 7400 cont.) Reassembly Fore end screw Affects accuracy Do not use swivel study that screws in place of FE screw, use barrel band Possible malfunctions Jamming - what causes this? Ammunition "hot" or high energy, light magnum loads Military surplus Dirty gun - chamber pitted from misuse Shouldering Care and cleaning Model 7600 Brief history including 760 Cycle of operation Similarities to 7400 Disassembly. Stock and fore end Receiver assembly 20 gauge shorgun receiver Action bar assembly Detachable magazine frigger assembly Common fire control Barrel assembly Locking lugs in barrel Barrel to receiver fit Reassembly Possible malfunctions Most reliable firearm we make Very few repairs Opens on firing - this is normal Care and cleaning No hot loads Chamber