

The BUSHNELL® contact information is Tel: +31 10 494 5767, Fax: +31 10 494 5770 and e-mail: [rmonster@bushnell.com](mailto:rmonster@bushnell.com).

**SDS Recall**

Privileged and Confidential – November 26, 2002

Model 710 – Safety Detent Spring Recall and Replacement Program  
Q & A – Consumer/Customer Service

Serial # Range Firearms with potential improperly manufactured springs  
71009425 – 71087773

**\*\* (Serial #'s outside of the range above, are not affected by this program.) \*\***  
(Only the Model 710 potentially effected by this program)

**1. Is this a recall?**

Yes, it is a voluntary recall of a limited number of guns. The recall applies only to those Model 710 rifles within the affected serial number range. Only those rifles may have been assembled with an improperly manufactured "Safety Detent Spring." No other Model 710 rifles and no other Remington firearms of any model, are affected by this recall.

**2.) Will this improperly manufactured "Safety Detent Spring" cause my gun to go off?**