

Jim Ronkainen

---

From: Ronkainen, Jim  
Sent: 02/18/2005 12:17:47 PM  
To: Norton, Vince  
CC:  
BCC:  
Subject: RE: M710 Parts List

Vince,

Please add one more part to your list of things to investigate - the SAP BOM doesn't include the safety pivot pin (F300932) as part of the receiver assembly insert complete (F300401) or the complete gun (27434). Are they using another part for this (300464)? I can't tell. I'm sooooo confused.....

Thanks,

Jim

---

From: Ronkainen, Jim  
Sent: Friday, February 18, 2005 11:54 AM  
To: Norton, Vince  
Subject: RE: M710 Parts List

Vince,

Can you check the sear too? SAP shows Ilion's sear 15666 being used without alteration while the P/L shows a different part numbers.

Thanks,

Jim

---

From: Ronkainen, Jim  
Sent: Friday, February 18, 2005 11:50 AM  
To: Norton, Vince  
Subject: M710 Parts List

Vince,

I'm comparing the current 710 trigger assembly (actually, receiver insert assembly complete) versus the

Subject to Protective Order - Williams v. Remington

BARBER 5.30.06R0000399

ETE00000398