

Customer Complaint

P No GUN EXAMINATION REPORT NUMBER: _____ MODEL: 700 ADLGENERAL CONDITION: NEW R #: 001648OUTSIDE WORK: SCOPE MOUNTED, SWIVELS DATE: 1-26-72RECOIL PAD FITTED.FROM: DUNN'S F&B, GDS, INC.

FIRED AMMO TYPE: _____

PEVELY, MISSOURI

& CONDITION: _____

GUN #: 332321PROOF: R.E.P. INSP.: D TEST: 49CODE: BL = 1/64HEADING: O.K.GA./CAL.: 3006BREECH OPENING: -CHECKED BY: C. PROSSERRECOIL SHOULDERS: O.K.

APPROVED: _____

CHAMBER: O.K.

APPROVED: _____

TEST: No

APPROVED: _____

COMPONENT CONDITION: (Damaged, Broken, Old Style)

APPROVED: _____

NO DAMAGED, BROKEN COMPONENTS. SEAR-CONNECTORENGAGEMENT .010 (MIN. .020) TRIGGER FULL = 3 1/2 (MIN. = 3 1/2)TRIGGER CLEARANCE ON CONNECTOR 1.087 M/D = 1.080CONNECTOR CLEARANCE ON TRIGGER 1.073 M/D = 1.074(.014 CLEARANCE WHERE .007 IS MAX.)COMPLAINT: FIRES WHEN SAFE IS RELEASEDINCIDENT: CONNECTOR FAILS TO RETRACT.PLAINTIFF'S
EXHIBIT

3262

COMMENTS: THE EXCESSIVE CLEARANCE BETWEEN CONNECTOR
AND TRIGGER ALLOWS THE CONNECTOR TO CREEP UP INTO
AN INTERFERENCE POSITION WHERE IT FAILS TO RETRACT
WITH THE SAFETY ON, WHEN THE SAFETY IS
RELEASED THE FIRING PIN FOLLOWS DOWN.

1 of 1