

Jim Ronkainen

---

**From:** Ronkainen, Jim  
**Sent:** 02/18/2005 11:49:59 AM  
**To:** Norton, Vince  
**CC:**  
**BCC:**  
**Subject:** M710 Parts List

Vince,

I'm comparing the current 710 trigger assembly (actually, receiver insert assembly complete) versus the new SPL for Ilion (don't ask why) and I noticed that the 710 trigger in the P/L is listed as 300483 with 300482 as the blank (p. 2 of P/L), but SAP calls out 109835. Could you please check this out (and fix the P/L to reflect reality, if necessary)?

Thanks!

Jim Ronkainen

Staff Engineer

Remington Arms Co. Inc.

R&D Technical Center

315 W. Ring Road

Elizabethtown, KY 42701

(270) 769-7613 (phone)

(270) 737-9576 (fax)

jim.ronkainen@remington.com

visit us at [www.remington.com](http://www.remington.com)

Subject to Protective Order - Williams v. Remington

BARBER 5.30.06R0008095

ETE00000404