

P... NO GUN EXAMINATION REPORT NUMBER: \_\_\_\_\_GENERAL CONDITION: GOODOUTSIDE WORK: NO

FIRED AMMO TYPE: \_\_\_\_\_

&amp; CONDITION: \_\_\_\_\_

PROOP: R.E.P.

INSP.: \_\_\_\_\_

TEST: 79HEADING: O.K.BREECH OPENING: -RECOIL SHOULDERS: O.K.CHAMBER: O.K.TEST: NO

COMPONENT CONDITION: (Damaged, Broken, Old Style)

MODEL: 700 BDLR # : 000999DATE: 1-12-72FROM: CADDIE LABAR'S

DISTR. CO.

DALLAS, PENN.GUN # : 232943CODE: WN = 8/66GA./CAL.: 280 REM.CHECKED BY: C. PROSSER

APPROVED: \_\_\_\_\_

APPROVED: \_\_\_\_\_

APPROVED: \_\_\_\_\_

APPROVED: \_\_\_\_\_

NO DAMAGED OR BROKEN COMPONENTS. TRIGGER PULL FOUR  
POUNDS, ENGAGEMENT .015, TRIGGER BINDING ON GUARD  
SLIGHTLY. GREASE-DIRT COATING ON HIDDEN PARTS  
INCLUDING INSIDE & OUTSIDE OF TRIGGER ASSEMBLY.

COMPLAINT: SOMETIMES IT WILL FIRE, OTHER TIMES IT WON'T, SOMETIMES  
IT WILL BE A DELAYED FIRING.

INCIDENT: SEAR DOES NOT RELEASE FIRING PIN.

**PLAINTIFF'S  
EXHIBIT**

3263

COMMENTS: THE CUSTOMER'S MALFUNCTION WAS DUPLICATED WITH  
STOCK IN PLACE BUT WORKED O.K. WITH S-S&S OFF.  
APPARENTLY THE TRIGGER-THROTTLE GUARD BIND  
COMBINED WITH THE TOO HEAVY LUBRICATION WAS  
THE CAUSE OF HIS TROUBLE.