

P. NO GUN EXAMINATION REPORT NUMBER: _____GENERAL CONDITION: NEWOUTSIDE WORK: SCOPE MOUNTED, REGULARSIGHTS REMOVED.FIRED AMMO TYPE: R.P.& CONDITION: ONE PERCED PRIMERPROOF: R.E.P.-B INSP.: 71 TEST: 49HEADING: O.K.BRESCH OPENING: -RECOIL SHOULDERS: O.K.CHAMBER: O.K.TEST: TEP ROUNDS OF 120 GR. WAD PERCED PRIMERS.

COMPONENT CONDITION: (Damaged, Broken, Old Style)

MODEL: 700 ADL.R # : 26180DATE: 12-21-71FROM: H.A.H. S&A, GDS, INC.AMARILLO, TEXAS.GUN # : 6332550CODE: CT-4/70GA./CAL.: 25-06 TCHECKED BY: C. PROBER

APPROVED: _____

APPROVED: _____

APPROVED: _____

APPROVED: _____

FIRING PIN POINT TOO FLAT. TRIGGER CONNECTORDAMAGED. SEAR-TRIGGER CONNECTOR ENGAGEMENT
.005COMPLAINT: RIFLE WILL NOT COCK.INCIDENT: FOLLOWS DOWN.PLAINTIFF'S
EXHIBIT

3264

COMMENTS: THE .010 UNDER MIN. ENGAGEMENT COMPLAINED WITH
BACKLASH FROM PERCED PRIMERS FORCE DOWN
THE CORNER OF THE TRIGGER CONNECTOR RESULTING
IN THE FOLLOW DOWN MALFUNCTION.

1 of 1