								8/	
								BARB	
								<b>8</b>	
								ガ	
								<u> </u>	
	****							ᇛ	
	43		3					Š	
				à				ō	
	_					1		٥	<b>,</b>
ET CTC MN MN	710	71030395 C	e errenamenteriore		FORWARDED TO PADUCAH SHOOTERS SUPPLY.	20629	\$10.25	1 151554	-
CT	710	71032739 1	2000000000 000		FORWARDED TO PADUCAH SHOOTERS SUPPLY.	20629	\$10.25	6 151553	-
GI GT	710	71032821 1	U-101		FORWARDED TO PADUCAH SHOOTERS SUPPLY.	20629	\$10.25	1,151611	<del> </del> -
<u></u>	710	7102101 -		terabereset prover	FORWARDED TO PADUCAH SHOOTERS SUPPLY.	20629	\$10.25	1,151555	<b>}</b>
	710	71016563	2000000	MAG RELEASE BROKEN:	INSPECTED AND SENT TO PADUCAH.	20017	\$28.02	11,136049 😂	ļ
GA GA	710 710	71009762 0 71019821 0		M23 BOLT CAME APART	PÖLISHED CHAMBER AND TEST FIRED. REFIT FIRING PIN ASSY & CHECKED HEAD SPACE.	20106	\$35.00 \$30.00,	1,149362 6 1,149360 <b>5</b> 1	ļ
MN	710	71016022 0		BROKEN MAG RELEASE.	SENT TO FACTORY, PADUCAH REPAIRED, RETURNED TO CUSTOMER.	20106 <sub>1</sub> 20017 <sub>1</sub>	\$28.02	1,149502	L
CA	710	71002843 0		M5	SENT TO FACTORY.	20106	\$28.52 <sub>1</sub>	1,149361	<u></u>
ICA	710	71002648 0		DEFECTIVE SCOPE.	SENT TO FACTORY	20106	\$23.83	1:149355	1
ICA	710	71013661 0		M23	SENT TO FACTORY.	20106	\$12.52	1:149358	i
ICA	710	71025333 0		M5	SENT TO FACTORY	20106	\$27.52	7:149356	,
ICA	710	710025307 -		BOLT ROUGH.	SENT TO FACTORY	20106	\$28.52	11149353	1
MI	710	71013664 0	4-01	M10	CLEANED & POLISHED CHAMBER AND TEST FIRED.	20108	\$43.00	11142123	
MI	710	71003969 0		M8	SENT TO FACTORY FOR SERVICE	20108	\$32.00	74 149114	-
MN	710	71004079 0	11-01	MALFUNCTIONS.	SENT TO PADUCAH, RETURNED TO CUSTOMER	20017	\$34.14	141149515	***************************************
MN	710	71011188 0	4-01	M5	SENT TO PADUCAH, SENT BACK TO CUSTOMER.	20017 <sup> </sup>	\$33.94 <sup>‡</sup>	1 149527	-
MN	710	71017063 0	5-01	M33	SENT TO PADUCAH.	20017 <sup>1</sup>	\$33.74 <sup>1</sup>	9 <sup>1</sup> 149526	ļ
CAN	710	71010514 0	3-01	DOESN'T ALWAYS GRAB SHELLS.	EXTRACTOR, CHECKED AND TEST FIRED	21040	. \$45.44	21 84041	1
ОН	710	71001519 0	1-01	SHOOTERS TO RETURN TO	SENT TO PADUCAH NAD RETURNED TO YOU INSTEAD OF US.	21060	<b>∜\$2</b> 3.75¹	6 <sup>3</sup> SH4760	1
ОН	710	71005701 0	1-01	PROPERLY, BOLT HANDLE BROKE	SENT TO PADUCAH SHOOTERS SUPPLY.	21060	<b>\$2</b> 3.75 <sup>1</sup>	0 <sup>1</sup> SH4622	j denne
ОН	710	71001519 0		CHECK OUT.	SENT TO PADUCAH SHOOTERS SUPPLY.	21060	\$23.75	0°SH4629	, }
ОН	710	71006860 0		LOCK FOR BOLT BROKEN.	SENT TO PADUCAH SHOOTERS SUPPLY.	21060	\$23.75	0,SH4568	
ОН	710	71011797 0		CUSTOMER NOT SATISIFIED.	SENT TO PADUCAH SHOOTERS SUPPLY.	21000	\$23.75	0 SH4508	ļ
ОН	710	71013213 0		CLEAN AND CHECK.	SENT TO PADUCAH SHOOTERS SUPPLY.	21060	\$23.75	0,SH4519	ļ
ЮН	710	71016668 0		OFF.	SENT TO PADUCAH SHOOTERS SUPPLY.	21060	\$23.75	0 SH4549	
OH	710	71017348 0		BROKEN.	SENT TO PADUCAH SHOOTERS SUPPLY.	21060	\$23.75	0 <sub>1</sub> SH4554	1_
OH	710	71020753 0		BAD BOLT.	SENT TO PADUCAH SHOOTERS SUPPLY.	21060	\$23.75	0 <sub>1</sub> SH4522	1
HO	710	71025258 0		30-06 BBL ON A 270 GUN.	SENT TO PADUCAH SHOOTERS SUPPLY.	21060 <sub>i</sub>	\$23.75	B <sub>1</sub> SH4630	1
¦OH ⊦OH	710 710	71028422 0 71028452 0		BOLT CAME APART. NEEDS TO BE CHECKED OUT.	SENT TO PADUCAH SHOOTERS SUPPLY. SENT TO PADUCAH SHOOTERS SUPPLY.	21060 <sub>1</sub> 21060:	\$23.75 <sub>f</sub> \$29.75 <sub>f</sub>	0 SH4624 0 SH4702	
IOH	710	71029920 0		TRIGGER GUARD BROKEN.	SENT TO PADUCAH SHOOTERS SUPPLY.	21060	\$23.75	0;SH4570	j ,
IOH	710	71029920 0		BOLT BROKEN.	SENT TO PADUCAH SHOOTERS SUPPLY.	21060	\$23.751	13;SH4627	1
IMI	710	71002071 0		M8	FIRED.	21000	\$26.50l	71141773	
ICT	710	71014340 0		1710	FORWARDED TO PADUCAH SHOOTERS SUPPLY.	20629	\$15.00i	11151096	
	, 10	7,0,7070 0			TOTAL ALGEBRA TO TABOUR PROTOCOLOGICAL CONTEST.	20020	ψ10.00°	1-101000	