

Williams v. Remington

BARBER - REM DOCSB0008983

MAE00008895

ITA	710	71019140	06-01	FAILS TO EJECT	CHANGED EJECTOR	21032	\$5.00	1	4079467
ITA	710	71019017	06-01	FAILS TO EJECT	CHANGED EJECTOR	21032	\$5.00	1	4079467
ITA	710	71017901	06-01	FAILS TO EJECT	CHANGED EJECTOR	21032	\$5.00	1	4079467
ITA	710	71019018	06-01	FAILS TO EJECT	CHANGED EJECTOR	21032	\$5.00	1	4079467
ITA	710	71023421	07-01	FAILS TO EJECT	CHANGED EJECTOR	21032	\$5.00	1	40814665
ITA	710	71024083	07-01	FAILS TO EJECT	CHANGED EJECTOR	21032	\$5.00	1	40814665
ITA	710	71025981	08-01	FAILS TO EJECT	CHANGED EJECTOR	21032	\$5.00	1	40814665
ITA	710	71022014	08-01	FAILS TO EJECT	CHANGED EJECTOR	21032	\$5.00	1	40814665
ITA	710	71024589	08-01	FAILS TO EJECT	CHANGED EJECTOR	21032	\$5.00	1	40814665
ITA	710	71024709	08-01	FAILS TO EJECT	CHANGED EJECTOR	21032	\$5.00	1	40814665
ITA	710	71019750	08-01	FAILS TO EJECT	CHANGED EJECTOR	21032	\$5.00	1	40814665
ITA	710	71026854	08-01	FAILS TO EJECT	CHANGED EJECTOR	21032	\$5.00	1	40814665
ITA	710	71026696	08-01	FAILS TO EJECT	CHANGED EJECTOR	21032	\$5.00	1	40814665
ITA	710	71025996	08-01	FAILS TO EJECT	CHANGED EJECTOR	21032	\$5.00	1	40814665
ITA	710	71023243	08-01	FAILS TO EJECT	CHANGED EJECTOR	21032	\$5.00	1	40814665
ITA	710	71026513	08-01	FAILS TO EJECT	CHANGED EJECTOR	21032	\$5.00	1	40814665
ITA	710	71024708	08-01	FAILS TO EJECT	CHANGED EJECTOR	21032	\$5.00	1	40814665
ITA	710	71024789	08-01	FAILS TO EJECT	CHANGED EJECTOR	21032	\$5.00	1	40814665
ITA	710	71024788	08-01	FAILS TO EJECT	CHANGED EJECTOR	21032	\$5.00	1	40814665
ITA	710	71026653	08-01	FAILS TO EJECT	CHANGED EJECTOR	21032	\$5.00	1	40814665
ITA	710	71026732	08-01	FAILS TO EJECT	CHANGED EJECTOR	21032	\$5.00	1	40814665
ITA	710	71026666	08-01	FAILS TO EJECT	CHANGED EJECTOR	21032	\$5.00	1	40814665
CA	710	71008698	03-01	LOADED.	GUN WITH A NEW SERIAL NUMBER (71052181). REF. ORDER # 452538.	21016	\$31.28	83	157839
CA	710	71008551	02-01	M145	GUN.	21016	\$28.79	1	157843
MN	710	71017802	05-01	MISS FIRES.	DISASSEMBLED BOLT AND CLEANED OIL OUT OF INSIDE OF BOLT. TEST	20017	\$47.95	1	149750
MN	710	71010344	03-01	HARD.	SAFETY, TEST FIRED OK.	20017	\$47.64	4	149780
MN	710	71010197	03-01	M5	REBLUED BOLT, REPAIRED EXTRACTOR FROM BINDING RIM OF SHELL	20017	\$53.64	1	149735
FL	710	71012192	04-01	LOCKED. NEITHER WILL WORK.	POLISHING OF THE BOLT BODY FIXED THE PROBLEM.	20030	\$33.12	7	083727
CA	710	71008992	02-01	M145	REFITTED FIRING PIN ASSY.	21016	\$30.00	1	157836
MS	710	71001987	12-00	WAREHOUSE CHECK.	WAREHOUSE CHECK.	107773	\$15.00	1	0
MS	710	71007064	02-01	WAREHOUSE CHECK.	WAREHOUSE CHECK.	107773	\$15.00	1	16/10/02
MS	710	71031385	09-01	WAREHOUSE CHECK.	WAREHOUSE CHECK.	107773	\$15.00	1	16/10/02
CAN	710	71024018	07-01	APART.	INSTALLED NEW CLIP LATCH, REASSEMBLED CLIP.	20212	\$81.54	1	1000124
NZ	710	71031089	10-01	M33	REPLACED STOCK.	21068	\$99.59	1	1137315
MS	710	71002559	12-00	WAREHOUSE CHECK.	WAREHOUSE CHECK.	107773	\$15.00	1	DK1546