

107773	\$15.00	1	DK1519
20023	\$29.39	0	110600
20023	\$90.93	29	110592
21087	\$49.59	5	532223
20630	\$25.65	47	030968
21087	\$39.24	1	531829
20023	\$25.89	1	110587
20630	\$65.00	32	030971
20023	\$35.17	5	161502

WAREHOUSE CHECK.
BOLT HANDLE BROKEN OFF - BOLT BODY RETURN TO PADUCAH
FAX IN ORDER 250
BRASS FROM EJECTOR SPRING. INSTALLED EXTRACTOR. TEST FIRED.
REPLACED BOLT STOP.
RETURNED TO FACTORY.
MART
STRIPPED AND REBLUED.
OPEN - CLOSED TESTED OK FOUND NO PROBLEM W/RIFLE

WAREHOUSE CHECK.
BOLT BROKEN - BOLT STICKS
MAG LATCH BROKEN.
WILL NOT EJECT. BOLT IS TIGHT.
BOLT PULLS OUT
WON'T FEED OUT OF THE CLIP.
RETRIEVER AND BARREL
IN SCOPE NOT RIGHT

MS 710
OR 710 71037506 11-01
OR 710 71029486 09-01
TX 710 71006530 01-01
CAN 710 71028055 08-01
TX 710 71010903 03-01
OR 710 71027349 08-01
CAN 710 7104103 -
OR 710 71007240 02-01

Subject to Protective Order - Williams v. Remington