

REPLACED BOLT, EXTRACTOR FLINGER AND EXTRACTOR.	104476	\$119.10	1	142633
REPLACED FRONT SIGHT AND SCREW.	104476	\$80.73	2	142640
REPLACED MAG DOCK ASSY, EXTRACTOR FLINGER AND EXTRACTOR.	104476	\$63.86	1	142611
REPLACED EXTRACTOR, SPRING & FLINGER AND TEST FIRED.	20301	\$20.63	5	140910
SENT TO FACTORY.	20801	\$35.00	3	1484
REPLACED EJECTOR AND MAG AND TEST FIRED.	20106	\$38.85	1	149368
REPLACED EJECTOR & REMOVED BURRS FROM CHAMBER AND TEST FIRED.	20106	\$32.15	1	149369
REMOVED BURRS FROM CHAMBER & REMOVED BURRS FROM CHAMBER AND TEST FIRED.	20106	\$32.15	1	149370
INSTALLED EJECTOR UPGRADE.	20801	\$13.50	1	131487
REPLACED HOLD OPEN RETAINING SPRING & EJECTOR AND TEST FIRED.	20106	\$36.00	1	149379
REPLACED BROKEN EJECTOR AND TEST FIRED.	20112	\$23.75	1	176561
REPLACED HOLD OPEN RETAINING SPRING & EJECTOR AND TEST FIRED.	20106	\$36.32	1	157825
REPLACED HOLD OPEN RETAINING SPRING & EJECTOR AND TEST FIRED.	20106	\$36.32	1	157819
FIT LATCH SPRING, REPLACED EJECTOR & REMOVED BURRS FROM CHAMBER AND TEST FIRED.	20106	\$34.73	1	157824
REPLACED MAG ASSY & EJECTOR AND TEST FIRED.	20106	\$43.47	1	157823
REPLACED EJECTOR & REMOVED BURRS FROM CHAMBER AND TEST FIRED.	20106	\$34.73	1	157822
REPLACED HOLD OPEN RETAINING SPRING & EJECTOR AND TEST FIRED.	20106	\$36.32	1	157821
ADJUSTED LATCH SPRING & REPLACED EJECTOR.	20106	\$39.83	1	157828
INSTALLED HOLD OPEN, SPRING & PIN AND TEST FIRED.	20106	\$41.11	1	157817
REPLACED HOLD OPEN RETAINING SPRING & EJECTOR AND TEST FIRED.	20106	\$34.73	1	157820
REPLACED EJECTOR AND TEST FIRED.	20106	\$34.73	1	157831
SENT TO FACTORY TWICE.	20106	\$54.10	3	157801
RETURNED TO FACTORY.	20607	\$4.00	1	96046
REPLACED MISSING EXTRACTOR SPRING & FLINGER AND TEST FIRED.	20607	\$20.29	3	96034
FIT NEW EXTRACTOR ASSY.	20607	\$20.97	1	96031
REASSEMBLED UNIT, INSTALLED AND TEST FIRED.	20607	\$21.00	3	96027
REPLACED FIRING PIN AND TESTED.	20607	\$28.34	4	96058
REPLACED EJECTOR AND TEST FIRED.	20106	\$34.73	1	157863
REPLACED EJECTOR, REMOVED BURRS FROM CHAMBER AND TEST FIRED.	20106	\$34.73	1	157857
REPLACED EJECTOR & REMOVED BURRS FROM CHAMBER AND TEST FIRED.	20106	\$34.73	1	157864
REPLACED EJECTOR & REMOVED BURRS FROM CHAMBER AND TEST FIRED.	20106	\$34.73	1	157856
REPLACED EJECTOR & MAG ASSY AND TEST FIRED.	20106	\$43.51	1	157862
REPLACED EJECTOR AND TEST FIRED.	20106	\$34.73	1	157855