

REPLACED STOCK ASSY, CHECKED OVER, CLEANED & OILED, SAFETY & FUNCTION TESTED.	20629	\$173.36	15	122695
REPLACED EJECTOR & EJECTOR, CHECKED OVER, CLEANED & OILED, SAFETY & FUNCTION TESTED.	20629	\$51.76	19	151305
REPLACED BOLT HANDLE, SPRING & FLINGER.	20629	\$51.16	34	151293
UPGRADED EJECTOR, SAFETY & FUNCTION CHECKED, INSTALLED EJECTOR, CHECKED OVER, CLEANED & OILED, SAFETY & FUNCTION TESTED.	20629	\$42.98	45	151341
DEROSTED BBL & OILED, CHECKED OVER, CLEANED & OILED, SAFETY & FUNCTION TESTED.	20629	\$40.75	22	151362
REPLACED EJECTOR, EXTRACTOR & MAG, CHECKED OVER, CLEANED & OILED, SAFETY & FUNCTION	20629	\$53.36	18	151373
REPLACED EJECTOR WITH NEW STYLE AND TEST FIRED.	20603	\$14.70	3	11339
INSTALLED NEW STYLE EJECTOR.	20030	\$17.23	58	83749
SENT TO FACTORY.	20030	\$27.15	19	83759
INSTALLED MISSING LAT, SPRING & FLINGER AND TEST FIRED.	20624	\$41.30	27	122327
TEST FIRED WITH SEVERAL DIFFERENT TYPES OF AMMO HAD NO JAMS.	20030	\$31.98	110	083766
REPLACED BOLT HANDLE AND EJECTOR.	20502	\$21.84	1	68709
INSTALLED NEW STYLE EJECTOR.	20502	\$12.31	1	68765
INSTALLED NEW STYLE EJECTOR.	20502	\$12.31	1	68766
FOUND REAR SIGHT HAD BEEN LOOSENED ALL THE WAY, ADJUSTED REAR SIGHT.	20300	\$40.00	77	111595
CLEANED UP SUMMER OF SUBSTANCE ON BUFFER BOLT, REINSTATED BUFFER AND TEST FIRED.	20300	\$50.00	1	125219
REPAIRED AS NECESSARY.	20300	\$45.00	34	111598
COULD NOT VERIFY COMPLAINT, TEST FIRED WITH NO PROBLEMS.	20300	\$45.00	8	111599
SHIPPED TO FACTORY.	20300	\$18.50	1	125230
RETURNED TO FACTORY.	20300	\$18.50	1	125228
SENT TO REMINGTON.	20300	\$18.50	5	125221
REPLACED BROKE EXT.	20308	\$30.10	39	139865
TOP OF RECEIVER HAD A ROUGH SPOT.	20308	\$33.50	7	139860
TIGHTENED UP BOLT HANDLE, ADJUSTED EJECTOR FURTHER INTO BOLT FACE AND TEST FIRED.	20800	\$29.00	28	111632
REPLACED MAGAZINE, ADJUSTED OPEN RETURN SPRING AND TEST FIRED.	21028	\$48.30	3	137127
METAL CLIP.	21028	\$21.53	1	137078
REPLACED EJECTOR, EXTRACTOR, FLINGER & SPRING AND TEST FIRED.	21028	\$25.77	1	137018
REPLACED EJECTOR, MAG BOX BRIDGE OPEN SPRING, REMOVED BURRS AT CHAMBER AREA AND TEST	21028	\$41.43	1	137112
REPLACED BBL AND TEST FIRED.	21028	\$64.06	14	137123
REPLACED EJECTOR & MAG BOX AND TEST FIRED.	21028	\$49.70	6	137125
REPLACED EJECTOR, EXTRACTOR & BOLT GUIDE RAILS AND TEST FIRED.	21028	\$32.83	1	137109
REPLACED EJECTOR & MAG BOX, REMOVED BURRS AT CHAMBER AREA AND TEST FIRED.	21028	\$39.86	1	137131
REPLACED MAG BOX AND TEST FIRED, REMOVED BURRS AT RIM AREA.	21028	\$36.03	1	137133