

REPLACED LINK PIN, STARED HEAD OF PIN AND TEST FIRED.	20108	\$25.00	15	142163
REPLACED EJECTOR AND TEST FIRED.	20108	\$21.16	24	142150
REPLACED BROKEN EJECTOR AND TESTED.	20108	\$42.16	107	132132
ADJUSTED EJECTOR, REPAIRED BOLT, HOLED OPEN SPRING.	20108	\$42.00	3	132141
REPLACED TRIGGER ASSY AND TEST FIRED.	21054	\$52.99	23	141186
REPLACED MAGAZINE AND TESTED.	21054	\$25.69	13	116850
UPDATED TO NEW EJECTOR AND TEST FIRED.	21054	\$21.56	3	134976
REPLACED EJECTOR, POLISHED CHAMBER AND TEST FIRED.	20108	\$65.97	2	149128
CLEANED & OILED DBL. CHAMBER, REPLACED EJECTOR AND TEST FIRED.	20108	\$46.17	4	149117
REPLACED EJECTOR AND TEST FIRED.	20108	\$46.17	7	149116
REPLACED EJECTOR AND TESTED.	20108	\$57.17	4	149115
INSTALLED NEW BOLT HANDLE, CLEANED, OILED OUT AND TEST FIRED.	21019	\$30.95	6	141785
REPLACED BOLT ASSY & EJECTOR.	21030	\$65.84	1	104249
POLISHED CHAMBER, INSTALLED NEW STYLE EJECTOR AND TESTED.	21030	\$22.23	1	104248
INSTALLED NEW STYLE EJECTOR AND TEST FIRED.	21019	\$40.25	13	141760
INSTALLED & ADJUSTED NEW EJECTOR.	21054	\$49.23	7	116873
CLEANED, OILED CHAMBER, INSTALLED EXTRACTOR, PLUNGER & SPRING AND TEST FIRED.	21019	\$30.30	12	141753
INSPECTED, REPLACED MAGAZINE AND TESTED	21054	\$24.52	22	98404
REPLACED BOLT & EJECTOR.	20108	\$116.06	4	149178
REPLACED EJECTOR, STONED HAMMER, OPENED DBL CHANNEL TO FREE FLOAT AND TEST FIRED	20108	\$66.59	6	162263
REASSEMBLED AND TEST FIRED	20108	\$35.00	1	142182
REPLACED EJECTOR, REPOSITIONED GEAR SPRING AND TEST FIRED.	20108	\$32.50	10	149159
REPLACED BOLT ASSY, UPDATED EJECTOR, CLEANED REC AREA, REPAIRED MAGAZINE AND TEST FIRED.	20108	\$122.90	8	142186
LUBED ACTION, CLEANED CHAMBER AND TESTED.	20108	\$35.00	3	149170
INSPECTED & TESTED, CLEANED CHAMBER, LUBED ACTION & RETESTED. RETAPPED SCOPE MT HOLES.	20108	\$61.65	1	149166
REPLACED EJECTOR, UPDATED AND TEST FIRED.	20108	\$38.85	3	149183
UPDATED TO NEW EJECTOR, TEST FIRED, REPLACED MAGAZINE	21054	\$44.00	27	098488
CLEANED, OILED OUT, OILED FINEST FIN AND TESTED.	21019	\$38.50	2	141806
REPLACED EJECTOR TO NEW STYLE	21054	\$38.73	20	098480
REASSEMBLED - TEST FIRED	21054	\$50.00	1	098487
ADJUSTED LINKAGE ON TRIGGER GROUP TO MOVE FREELY, ADJUSTED CLIP LATCH TO HOLD TIGHTER	20017	\$40.45	1	149509
REPLACED CLIP, REPAIRED EJECTOR AND TEST FIRED.	20017	\$39.76	1	136052
REPAIRED EJECTOR, ADJUSTED TRIGGER LINKAGE AND TEST FIRED.	20017	\$44.19	1	136053