

GROUND EJECTOR FOR BOLT CLEARANCE, INSTALLED NEW TYPE OF EJECTOR, CLEANED, CHECKED AND INSTALLED BOLT ASSY & NEW TYPE EJECTOR, CLEANED, CHECKED AND TEST FIRED.	21060	\$50.25	4	SH4776
INSTALLED NEW STYLE EJECTOR, REPLACED BOLT ASSY & NEW BOLT HANDLE, CLEANED, CHECKED AND INSTALLED EXTRACTOR, FEEDER & SPRING AND MAG BOX ASSY, CLEANED, CHECKED AND TEST FIRED.	21060	\$81.09	1	SH4752
REPLACED BOLT ASSY & BOLT HANDLE, GROUND NEW STYLE EJECTOR, CLEANED, CHECKED AND TEST GROUND EJECTOR FOR BOLT CLEARANCE, INSTALLED NEW TYPE OF EJECTOR, CLEANED, CHECKED AND	21060	\$91.07	6	SH4759
GROUND EJECTOR, CLEANED, CHECKED AND TEST FIRED.	21060	\$61.56	2	SH4751
INSTALLED NEW TYPE OF EJECTOR, REPLACED MAGAZINE, GROUND EDGE OF EJECTOR, CLEANED INSTALLED NEW TYPE OF EJECTOR, CLEANED, CHECKED AND TEST FIRED.	21060	\$83.84	1	SH4765
REPLACED STR ASSY, INSTALLED NEW STYLE EJECTOR & REPLACED REAR SIGHT, CLEANED, INSTALLED NEW TYPE OF EJECTOR, CLEANED, CHECKED AND TEST FIRED.	21060	\$53.48	4	SH4779
REPLACED BOLT ASSY & BOLT HANDLE, CLEANED, CHECKED AND TEST FIRED.	21060	\$47.75	1	SH4817
CLEANED, CHECKED AND TEST FIRED.	21060	\$55.18	1	SH4820
GROUND EJECTOR & GROVE IN BOLT, CLEANED, CHECKED AND TEST FIRED.	21060	\$42.48	7	SH4832
INSTALLED NEW TYPE OF EJECTOR, CLEANED, CHECKED AND TEST FIRED.	21060	\$86.49	20	SH4786
REPLACED BOLT ASSY & BOLT HANDLE, CLEANED, CHECKED AND TEST FIRED.	21060	\$48.48	6	SH4835
CLEANED, CHECKED AND TEST FIRED.	21060	\$84.84	7	SH4830
GROUND EJECTOR & GROVE IN BOLT, CLEANED, CHECKED AND TEST FIRED.	21060	\$30.75	1	SH4850
INSTALLED NEW TYPE OF EJECTOR, CLEANED, CHECKED AND TEST FIRED.	21060	\$40.75	1	SH4854
INSTALLED NEW TYPE OF EJECTOR, REPLACED BOLT HANDLE & BOLT ASSY, CLEANED, CHECKED AND TEST FIRED.	21060	\$43.98	1	SH4851
REPLACED EXTRACTOR, FEEDER & SPRING, INSTALLED NEW TYPE OF EJECTOR, CLEANED, CHECKED AND TEST FIRED.	21060	\$92.57	4	SH4843
REPLACED TRIGGER HOUSING, CLEANED, CHECKED AND TEST FIRED.	21060	\$55.59	3	SH4886
INSTALLED EXTRACTOR, SPRING & FEEDER, CLEANED, CHECKED AND TEST FIRED.	21060	\$76.48	4	SH4877
GROUND EJECTOR SIDE, CLEANED, CHECKED AND TEST FIRED.	21060	\$49.36	1	SH4875
GROUND SIDE OF EJECTOR, CLEANED, CHECKED AND TEST FIRED.	21060	\$42.25	1	SH4867
GROUND SIDE OF EJECTOR, CLEANED, CHECKED AND TEST FIRED.	21060	\$45.75	1	SH4868
GROUND SIDE OF EJECTOR, CLEANED, CHECKED AND TEST FIRED.	21060	\$40.75	4	SH4878
CLEANED, CHECKED AND TEST FIRED.	21060	\$30.75	4	SH4865
REPLACED BOLT ASSY, CLEANED, CHECKED AND TEST FIRED.	21060	\$85.36	4	SH4861
GROUND SIDE OF NEW TYPE EJECTOR, CLEANED, CHECKED AND TEST FIRED.	21060	\$41.75	4	SH4860
REPLACED TRIGGER ASSY, CLEANED, CHECKED AND TEST FIRED.	21060	\$99.48	16	SH4856
CLEANED, CHECKED AND TEST FIRED.	21060	\$30.75	4	SH4866
REPLACED CLIP, BOLT ASSY & EJECTOR. REPLACED BOLT ASSY, INSTALLED NEW STYLE EJECTOR, CLEANED, CHECKED AND TEST FIRED.	21060	\$98.30	13	121404
GROUND SIDE OF EJECTOR FOR BOLT CLEARANCE, ADJUSTED RECOIL SPRING GUIDE, CLEANED, INSTALLED NEW TYPE OF EJECTOR, CLEANED, CHECKED AND TEST FIRED.	21060	\$61.75	16	SH4853
DEAD-BLANKED BOLT ASSY, CLEANED, CHECKED AND TEST FIRED.	21060	\$45.75	5	SH4892
REPLACED STOCK, CLEANED, CHECKED AND TEST FIRED.	21060	\$42.98	2	SH4895
	21060	\$81.75	26	SH4845
	21060	\$92.74	26	SH4847