

INSTALLED NEW TYPE EJECTOR, INLET STUCK PROPERLY, CLEANED, CHECKED AND TEST FIRED.	21060	\$56.75	6	SH4890
GROUND SIDE OF EJECTOR TO CLEAR BOLT, CLEANED, CHECKED AND TEST FIRED.	21060	\$42.25	5	SH4893
INSTALLED NEW TYPE EJECTOR, CLEANED, CHECKED AND TEST FIRED.	21060	\$59.98	3	SH4897
REPLACED TRIGGER ASSY & NEW TYPE EJECTOR, CLEANED, CHECKED AND TEST FIRED.	21060	\$68.21	2	SH4904
REPLACED TRIGGER HOUSING & MAGAZINE, CLEANED, CHECKED AND TEST FIRED.	21060	\$94.18	1	SH4917
REPLACED MISSING SPRING, EJECTOR, EXTRACTOR, PLUNGER & SPRING, CLEANED, CHECKED & TEST	21060	\$54.37	6	121414
GROUND EJECTOR SIDE, CLEANED, CHECKED AND TEST FIRED.	21060	\$40.75	3	SH4988
INSTALLED NEW TYPE EJECTOR, REPLACED BOLT ASSY, CLEANED, CHECKED AND TEST FIRED.	21060	\$97.59	3	SH4969
INSTALLED NEW TYPE EJECTOR, REPLACED MAGAZINE, CLEANED, CHECKED AND TEST FIRED.	21060	\$55.68	1	SH4971
NOTHING WRONG WITH GUN.	21060	\$35.25	13	SH4915
REPLACED BOLT ASSY, CLEANED, CHECKED AND TEST FIRED.	21060	\$75.52	22	SH4898
INSTALLED NEW TYPE EJECTOR, CLEANED, CHECKED AND TEST FIRED.	21060	\$42.98	2	SH4934
INSTALLED NEW TYPE EJECTOR, CLEANED, CHECKED AND TEST FIRED.	21060	\$42.98	2	SH4933
REPLACED BOLT ASSY AND EJECTOR.	21060	\$40.84	16	48538
INSTALLED EXTRACTOR, SPRING & PLUNGER, CLEANED, CHECKED AND TEST FIRED.	21060	\$45.86	2	SH4938
INSTALLED MISSING EXTRACTOR ASSY.	21060	\$54.37	6	121429
REPLACED MAGAZINE, INSTALLED NEW TYPE EJECTOR, CLEANED, CHECKED AND TEST FIRED.	21060	\$54.68	1	SH4947
DO NOT SEND THIS GUN BACK, THERE IS NOTHING WRONG WITH THIS GUN, CLEANED, CHECKED AND	21060	\$32.50	23	SH4914
INSTALLED NEW TYPE EJECTOR, CLEANED, CHECKED AND TEST FIRED.	21060	\$42.98	2	SH4859
REPLACED MAGAZINE & EJECTOR, CLEANED, CHECKED AND TEST FIRED.	21060	\$56.18	1	SH4944
REPLACED TRIGGER HOUSING, CLEANED, CHECKED AND TEST FIRED.	21060	\$85.98	4	SH4998
INSTALLED NEW MAGAZINE, REPLACED BOLT ASSY, CLEANED, CHECKED AND TEST FIRED.	21060	\$94.14	6	SH4994
REPLACED GIFT OF BOLT ASSY, GROUND CARTRIDGE EJECTOR, CLEANED, CHECKED AND TEST FIRED.	21060	\$105.64	7	SH4989
REPLACED GIFT, GROUND EJECTOR CARTRIDGE, TOOK TIMING PIN OUT OF BOLT, CLEANED, CHECKED AND TEST	21060	\$60.53	12	SH4986
INSTALLED NEW EJECTOR, CLEANED, CHECKED AND TEST FIRED.	21060	\$52.98	5	SH4999
REPLACED TRIGGER HOUSING, INSTALLED NEW STYLE EJECTOR.	21060	\$99.71	5	151461
INSTALLED NEW EJECTOR, ADJUSTED TRIGGERING, CLEANED, CHECKED, TEST FIRED OK.	21060	\$79.48	21	151459
INSTALLED NEW STYLE EJECTOR, SAFETY & TEST FIRED.	21047	\$18.73	3	128852
INSTALLED NEW STYLE EJECTOR, SAFETY & TEST FIRED.	21047	\$35.25	33	132570
INSTALLED NEW STYLE EJECTOR, SAFETY & TEST FIRED.	21047	\$29.58	5	132571
REPLACED TRIGGER HOUSING ASSY, INSTALLED NEW STYLE EJECTOR, SAFETY & TEST FIRED.	21047	\$68.81	5	132574
REPLACED DEFECTIVE SPRING PIN, INSTALLED NEW STYLE EJECTOR, SAFETY & TEST FIRED.	21047	\$41.80	5	132575
REPLACED EJECTOR, SAFETY & TEST FIRED.	21047	\$29.95	8	143527