

|                                                                                                                                                                               |        |          |    |        |
|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------|----------|----|--------|
| FUNCTIONS & SAFETY CHECKED, REATTACHED SPRING IN TRIGGER MECHANISM AND TEST FIRED.                                                                                            | 20510  | \$33.73  | 14 | 137638 |
| FUNCTIONS & SAFETY CHECKED AND TEST FIRED.                                                                                                                                    | 20510  | \$28.73  | 20 | 137636 |
| REPLACED BOLT HANDLE, FUNCTIONS & SAFETY CHECKED.                                                                                                                             | 20510  | \$32.15  | 30 | 137625 |
| FUNCTIONS & SAFETY CHECKED AND TEST FIRED.                                                                                                                                    | 20510  | \$23.27  | 35 | 137617 |
| REPLACED MAGAZINE.                                                                                                                                                            | 20510  | \$43.97  | 34 | 137548 |
| FUNCTIONS & SAFETY CHECKED AND TEST FIRED.                                                                                                                                    | 20510  | \$57.71  | 34 | 137663 |
| REPLACED EJECTOR, ADJUSTED EXTRACTOR.                                                                                                                                         | 20510  | \$67.29  | 4  | 156451 |
| FUNCTIONS & SAFETY CHECKED, CLEANED TRIGGER MECH, REPLACED MAGAZINE AND TEST FIRED.                                                                                           | 21052  | \$20.60  | 3  | 156464 |
| REPLACED BOLT WITH NEW EXTRACTOR ASSY AND TEST FIRED.                                                                                                                         | 21052  | \$41.65  | 7  | 156470 |
| REPAIRED LOOSE BOLT HANDLE RETAINER & MADE A FIT NEW RETAINER RIVET AND TESTED.                                                                                               | 21087  | \$38.52  | 21 | 57412  |
| REPLACED EXTRACTOR & MAG ASSY, TESTED.                                                                                                                                        | 21123  | \$20.67  | 38 | 137429 |
| CHECKED EXTRACTOR, DBL. CHAMBER, TRIGGER ASSY, BOLT ASSY, MAGAZINE, INSTALLED EJECTOR.                                                                                        | 21123  | \$12.00  | 23 | 137437 |
| REPLACED EJECTOR.                                                                                                                                                             | 21087  | \$36.19  | 21 | 1256   |
| SHIPPED GUN BACK TO CUSTOMER AFTER FULL INSPECTION SHOWED NO PROBLEMS.                                                                                                        | 21087  | \$24.03  | 5  | 1188   |
| CHECKED OVERALL, REPLACED BROKEN BOLT PLATE, TESTED FOR FEED AND FUNCTION, TEST FIRED AND REINST. SPRING, INSTALLED EJECTOR AND TEST FIRED, CHECKED ALL FUNCTIONS FOR SAFETY. | 21017  | \$21.50  | 7  | 88632  |
| TEST FIRED, SUSPECT AMMO PROBLEM.                                                                                                                                             | 21017  | \$17.50  | 5  | 69932  |
| REINSTALLED BOLT PLATE & TEST FIRED, CHECKED OVER.                                                                                                                            | 21069  | \$27.11  | 1  | 69693  |
| REPLACED EXTRACTOR ASSY AND TEST FIRED.                                                                                                                                       | 21125  | \$38.79  | 51 | 141310 |
| REPLACED EXTRACTOR, PLUNGER & SPRING.                                                                                                                                         | 20210  | \$7.45   | 35 | 108655 |
| POLISHED CHAMBER, CLEANED & DEBURRED PARTS                                                                                                                                    | 20959  | \$59.62  | 30 | 139082 |
| REPLACED PLUNGER, REINSTALLED EXTRACTOR.                                                                                                                                      | 20959  | \$31.86  | 79 | 139083 |
| REPLACED TRIGGER HOUSING ASSY AND TEST FIRED.                                                                                                                                 | 21123  | \$14.00  | 2  | 137467 |
| REPLACED EXT.                                                                                                                                                                 | 21017  | \$18.25  | 5  | 164053 |
| SAFETY WORKS CORRECTLY WITH REUSE TO TURN IT IN THE POSITION.                                                                                                                 | 21125  | \$46.83  | 95 | 127668 |
| CHECK ADJUST CARRIER, CHECKOUT, TEST FIRE                                                                                                                                     | 21125  | \$63.40  | 74 | 141315 |
| CHECKED THROUGHOUT, REPLACED PARTS, TEST FIRED- OK.                                                                                                                           | 21087  | \$65.95  | 52 | 531109 |
| REPLACED PARTS, TEST FIRED - OK                                                                                                                                               | 21087  | \$46.91  | 2  | 532212 |
| INSTALLED NEW MAGAZINE CATCH, CHECKED ALL COMPONENTS FOR FUNCTION AND SAFETY. TEST TAPPED OVERSIZE AND WRT. OF BASE TO OVERSIZE                                               | 107415 | \$11.50  | 24 | 134534 |
| SCREWS- LOCTITE MOUNT                                                                                                                                                         | 20960  | \$116.24 | 1  | 25297  |
| POURED OIL BACK AND TEST FIRED, PERFORMED SAFETY & FUNCTION TESTS.                                                                                                            | 20960  | \$53.34  | 1  | 25294  |
| REPLACED TRIGGER ASSY, EXTRACTOR & SPRING AND MAGAZINE.                                                                                                                       | 20960  | \$127.44 | 24 | 25290  |
| REMOVED BOLT, REPLACED EXTRACTOR, PLUNGER & SPRING, REASSEMBLED.                                                                                                              | 20960  | \$47.74  | 1  | 25285  |
| REPLACED BOLT REAR SIGHT & SCREWS AND TESTED.                                                                                                                                 | 20960  | \$79.49  | 1  | 25280  |
| REPAIRED WAS NOT TO ALLOW LOCKING IN POSITION, REPLACED REAR SIGHT SLIDE SCREW.                                                                                               |        |          |    |        |
| REPLACED TRIGGER ASSY, REINSTALLED BUFFER.                                                                                                                                    |        |          |    |        |