

Customer Complaint

P.I. NA GUN EXAMINATION REPORT NUMBER: _____ MODEL: 700 BDL
GENERAL CONDITION: NEW R #: 15003
OUTSIDE WORK: TRIGGER PULL REDUCED TO DATE: 7-30-71
ONE POUND. FROM: UNITED DIST.
FIRED AMMO TYPE: _____ GALVESTON, TEXAS
& CONDITION: _____ GUN #: 6408400
PROOF: R.E.P. INSP.: 74 TEST: 98 CODE: LO = 2/71
HEADING: O.K. EX./CAL.: 270 WIN.
BREECH OPENING: - CHECKED BY: C. PROSSER
RECOIL SHOULDERS: O.K. APPROVED: _____
CHAMBER: O.K. APPROVED: _____
TEST: No APPROVED: _____
COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: _____

ADJUSTING SCREW FOR TRIGGER PULL UNSEALED
AND ADJUSTMENT ALTERED.

COMPLAINT: FIRING PIN ENGAGES & FIRES WHEN BOLT IS
PUSHED FORWARD.

INCIDENT: FOLLOW DOWN

PLAINTIFF'S
EXHIBIT
3270

COMMENTS: WHEN TRIGGER PULL WAS CORRECTED ENGAGE-
MENT OF SEAR AND TRIGGER CONNECTOR WAS .025-
MIN. IS .015 WITH TRIGGER PULL REDUCED THE
SPRING WILL NOT RETRACT THE TRIGGER CONNECTOR
CORRECTLY AND FOLLOW DOWN MAY RESULT.

1 of 1