

KY	710	71004278	01-01	M5	UPDATED.	21072	\$14.00	4 150617
KY	710	71004901	01-01	M5	BOLT BODY.	21072	\$14.00	8 150660
KY	710	71002140	01-01	BAD SCOPE, FIRING PIN BROKEN.	UPDATED.	21072	\$14.00	5 150680
KY	710	71005084	01-01	M5	BOLT BODY.	21072	\$14.00	3 150688
KY	710	71003191	01-01	M5	BOLT BODY.	21072	\$14.00	3 150689
KY	710	71003960	01-01	TRIGGER BENT.	UPDATED.	21072	\$14.00	3 150629
KY	710	71005134	01-01	BOLT STOP.	UPDATED.	21072	\$14.00	4 150627
KY	710	71006142	01-01	M5	CHECK HEADSPACE, TEST FIRED AND UPDATED.	21072	\$17.00	3 150637
KY	710	71002822	01-01	M5	UPDATED.	21072	\$14.00	4 150616
KY	710	71004368	01-01	SAFETY HARD.	UPDATED.	21072	\$14.00	4 150711
KY	710	71001814	01-01	BOLT HANDLE FELL OFF.	REPLACED BOLT.	21072	\$14.00	1 150701
KY	710	71001823	01-01	TRIGGER GUARD.	STOCK AND BOLT STOP SPRING.	21072	\$14.00	1 150694
OK	710	71004368	01-01	SAFETY HARD TO OPERATE.	SENT TO PADUCAH FOR REPAIRS.	21047	\$19.95	28 143702
OK	710	71001814	01-01	BOLT HANDLE BROKE OFF.	SENT TO PADUCAH FOR REPAIRS.	21047	\$20.07	14 143705
OH	710	71004286	01-01	BOLT ACTION BROKE OFF.	RETURNED TO FACTORY FOR REPAIR.	21060	\$44.50	19 SH4648
AL	710	71004250	01-01	RETURN TO PADUCAH.	RETURNED TO PADUCAH.	21056	\$8.50	1 141662
VA	710	71002800	01-01	BROKEN BOLT HANDLE.	SHIPPED TO PADUCAH SHOOTERS SUPPLY.	20960	\$28.00	15 25289
CT	710	71005469	01-01		FORWARDED TO PADUCAH SHOOTERS SUPPLY.	20629	\$10.25	1 151613
CT	710	71004143	01-01		FORWARDED TO PADUCAH SHOOTERS SUPPLY.	20629	\$10.25	9 151791

Subject to Protective Order - Williams v. Remington