

CT	710	71003191	01-01		FORWARDED TO PADUCAH SHOOTERS SUPPLY.	20629	\$10.25	2 151514
CT	710	71004901	01-01		FORWARDED TO PADUCAH SHOOTERS SUPPLY.	20629	\$10.25	2 151516
MN	710	71004079	01-01	MALFUNCTIONS	SENT TO PADUCAH, RETURNED TO CUSTOMER.	20017	\$34.14	14 149515
MI	710	71003969	01-01	M8	SENT TO FACTORY FOR SERVICE.	20108	\$32.00	74 149114
OH	710	71005701	01-01	BOLT ASSY NOT OPERATING PROPERLY, BOLT HANDLE BROKE	SENT TO PADUCAH SHOOTERS SUPPLY.	21060	\$23.75	0 SH4622
OH	710	71001519	01-01	CHECK OUT.	SENT TO PADUCAH SHOOTERS SUPPLY.	21080	\$23.75	0 SH4629
OH	710	71001519	01-01	HAD LABEL FROM PADUCAH SHOOTERS TO RETURN TO	SENT TO PADUCAH NAD RETURNED TO YOU INSTEAD OF	21080	\$23.75	6 SH4760
MI	710	71002071	01-01	M8	DEBURRED EXTRACTOR & EJECTOR, DEBURRED BOLT	21019	\$26.50	7 141773
CT	710	71003066	01-01		FORWARDED TO PADUCAH SHOOTING SUPPLY.	20629	\$10.25	12 151077
KY	710	71005428	01-01	BOLT STOP & SPRING.	BOLT STOP AND SPRING	21072	\$14.00	6 124025
KY	710	71004085	01-01	UPDATE.	UPDATED.	21072	\$21.25	4 124006
KY	710	71004772	01-01	M5.	UPDATED.	21072	\$14.00	7 124018
KY	710	71005083	01-01	DEFECTIVE SCOPE & UPDATE. SAFETY DIFFICULT TO ENGAGE.	UPDATED, REPLACED REC INSERT ASSY.	21072	\$14.00	7 124021
KY	710	71002806	01-01	UPDATE.	UPDATED.	21072	\$14.00	1 124037
KY	710	71004188	01-01	FIRING PIN ASSY BLEW OUT WHEN FIRED, UPDATE.	UPDATED, TEST FIRED.	21072	\$16.25	4 150555
KY	710	71004092	01-01	BROKEN BOLT STOP.	UPDATED.	21072	\$14.00	1 124033
KY	710	71004027	01-01	M5	UPDATED.	21072	\$14.00	1 124036
KY	710	71003585	01-01	UPDATE.	UPDATED AND REPLACED REC INSERT.	21072	\$14.00	6 150742
KY	710	71004079	01-01	UPDATE, BOLT STOP.	UPDATED.	21072	\$14.00	5 150745

Subject to Protective Order: Williams v. Remington

BARBER - REM DOCB0010177

MAE00010093