

Subject to Protective Order - Williams v. Remington

KY	710	71003989	01-01	UPDATE, BOLT STOP BROKEN, EXTRACTOR LOOSE.	UPDATED.	21072	\$14.00	5 150744
KY	710	71001850	01-01	SCOPE BENT, UPDATE.	UPDATED.	21072	\$14.00	6 150749
KY	710	71005948	01-01	BOLT STOP	REPLACED BOLT STOP.	21072	\$14.00	4 150454
KY	710	71003888	01-01	M5	UPDATED.	21072	\$14.00	3 150487
KY	710	71004199	01-01	UPDATE.	UPDATED.	21072	\$14.00	8 150544
KY	710	71005166	01-01	UPDATE.	UPDATED.	21072	\$14.00	4 150471
KY	710	71003995	01-01	UPDATE.	UPDATED.	21072	\$14.00	7 150488
KY	710	71003691	01-01	BAD BOLT STOP.	ADDING BOLT-STOP SPRING	21072	\$14.00	7 150484
KY	710	71004996	01-01	UPDATE.	UPDATED.	21072	\$14.00	7 150494
KY	710	71004250	01-01	M9	CLEANED EJECTOR AND TESTED.	21072	\$14.00	3 150734
KY	710	71005119	01-01	BOLT STOP.	REPLACED BOLT STOP.	21072	\$14.00	3 150732
KY	710	71005589	01-01	M5	UPDATED.	21072	\$14.00	1 150721
KY	710	71004424	01-01	SAFETY HARD, SAFETY ON BOLT NOT WORKING.	UPDATED.	21072	\$14.00	1 150719
KY	710	71005168	01-01	FIRING PIN ASSY BROKEN.	REPLACED FIRING PIN ASSY.	21072	\$14.00	1 150716
KY	710	71001473	01-01	MAG LATCH BROKE.	UPDATED.	21072	\$14.00	1 150536
KY	710	71004034	01-01		REPLACED STOCK AND ADDED BOLT STOP CLIP.	21072	\$18.00	7 150520
KY	710	71004309	01-01	M5	UPDATED.	21072	\$14.00	10 150547
KY	710	71003688	01-01	UPDATE.	UPDATED.	21072	\$14.00	210 150545
KY	710	71005469	01-01	UPDATE.	UPDATED.	21072	\$14.00	7 150479