

KY	710	71008883	03-01	BOLT STOP.	UPDATED.	21072	\$14.00	3 150830
KY	710	71010820	03-01	M5	UPDATED.	21072	\$14.00	4 150708
KY	710	71010301	03-01	M5	UPDATED.	21072	\$14.00	1 150703
KY	710	71009349	03-01	BOLT STOP.	REPLACED BOLT STOP.	21072	\$14.00	1 150700
NE	710	71010440	03-01	BOLT STICKS.	SHIPPED TO PADUCAH.	21106	\$26.87	9 139218
AL	710	71010615	03-01	SENT TO FACTORY.	SENT TO FACTORY.	21056	\$8.50	1 138601
OK	710	71008826	03-01	SCOPE LENS LOOSE INSIDE	SENT TO PADUCAH.	21047	\$35.44	6 143716
OK	710	71008533	03-01	BOLT HANDLE BROKEN.	SENT TO PADUCAH.	21047	\$20.07	35 143714
CA	710	71009762	03-01	M23	POLISHED CHAMBER AND TEST FIRED	20106	\$35.00	1 149362
CA	710	71002843	03-01	M5	SENT TO FACTORY.	20106	\$28.52	1 149361
CA	710	71008688	03-01	DEFECTIVE SCOPE.	SENT TO FACTORY.	20106	\$23.83	1 149355
CAN	710	71010514	03-01	HARD TO CLOSE ON LIVE RD. DOESN'T ALWAYS GRAB SHELLS.	ADJUSTED FIRING PIN KEEPER IN BOLT, ADJUSTED BOLT BODY.	21040	\$45.44	21 84041
SC	710	71010038	03-01	CUSTOMER CAN'T INSTALL BOLT IN RIFLE.	INSTALLED BOLT & EXPLAINED TO CUSTOMER WHY IT WOULD	21044	\$10.00	1 150334
KY	710	71007915	03-01	M5	REPLACED BOLT HANDLE.	21072	\$14.00	7 124019
KY	710	71010822	03-01	BOLT CLOSSES HARD OVER SHELL.	UPDATED.	21072	\$17.50	4 124007
KY	710	71010563	03-01	MAG RELEASE BROKEN.	REPLACED STOCK AND UPDATED.	21072	\$14.00	6 124028
KY	710	71008392	03-01	MAG LATCH BROKEN.	REPLACED MAG LATCH.	21072	\$14.00	4 150755
KY	710	71008533	03-01	M5	REPLACED BOLT HANDLE.	21072	\$14.00	4 150753
KY	710	71009754	03-01	BOLT CAME APART & LOSE BOLT ASSY PIN.	REPLACED BOLT ASSY PIN.	21072	\$14.00	4 150752

Subject to Protective Order - Williams v. Remington

BARBER - REM DOCSB0010182

MAE00010098