

Subject to Protective Order - Williams v. Remington

CH	710	71013213	04-01	CLEAN AND CHECK.	SENT TO PADUCAH SHOOTERS SUPPLY.	21060	\$23.75	0 SH4519
KY	710	71011399	04-01	M5	UPDATED.	21072	\$18.00	4 150539
KY	710	71013692	04-01	M5	UPDATED.	21072	\$14.00	1 124030
KY	710	71014308	04-01	ISS SYSTEM WOULD NOT STAY LOCKED IN FIRING POSITION. ACTION	REPLACED BOLT BODY. TRIED DIFFERENT EXTRACTOR.	21072	\$16.25	7 124022
KY	710	71013238	04-01	M5	TRIED NEW BOLT HEAD AND	21072	\$14.00	5 150748
KY	710	71011413	04-01	M5	UPDATED.	21072	\$14.00	2 150464
KY	710	71011286	04-01	CUSTOMER REQUESTED FUNCTION & SAFETY TEST.	TESTED FUNCTION & SAFETY, ALL OK.	21072	\$14.00	2 150461
KY	710	71012289	04-01	BOLT STOP BAD. TRIGGER RELEASES ON ITS OWN	UPDATED.	21072	\$19.00	4 150466
KY	710	71011188	04-01	M5	REPLACED BOLT BODY.	21072	\$14.00	1 150652
KY	710	71012418	04-01	STIFF BOLT.	UPDATED.	21072	\$14.00	7 150482
KY	710	71011662	04-01	BOLT STICKING.	REMOVED BURR FROM BOLT HEAD AND TESTED.	21072	\$14.00	7 150498
KY	710	71012234	04-01	M5	UPDATED.	21072	\$14.00	7 150495
KY	710	71011596	04-01	FIRING PIN ASSY SAFETY WOULD NOT LOCK.	UPDATED.	21072	\$14.00	1 150729
KY	710	71014128	04-01		SENT NEW BOLT ASSY PER REMINGTON.	21072	\$14.00	1 150725
KY	710	71014314	04-01	RETURN.	CHECKED SAFETY & FUNCTION.	21072	\$14.00	1 150534
KY	710	71012344	04-01	BOLT STIFF.	NEW BOLT BODY.	21072	\$14.00	4 150550
KY	710	71013432	04-01	BOLT STOP BAD.	REPLACED BOLT STOP.	21072	\$14.00	2 150571
MN	710	71013432	04-01	BOLT LATCH.	SENT TO PADUCAH. CHECKED GUN OUT. SENT TO	20017	\$33.74	8 149617
CA	710	71013421	04-01	CHAMBER DEFECTIVE.	FACTORY.	20106	\$45.29	1 149389