

KY	710	71018752	06-01	BROKEN TRIGGER GUARD.	REPLACED BROKEN TRIGGER GUARD.	21072	\$14.00	6 150741
KY	710	71018568	06-01	M23	TESTED, CLOSED HARD OR NOT AT ALL. REPLACED EXTRACTOR.	21072	\$14.00	2 150462
KY	710	71022158	06-01	FEEDING PROBLEMS.	ONLY HAPPENS WITH WINCHESTER SILVER TIPS &	21072	\$14.00	11 150469
KY	710	71018582	06-01	MAG LATCH BROKEN.	REPLACED STOCK ASSY.	21072	\$14.00	1 150717
KY	710	71019966	06-01	MAG LATCH BROKEN.	REPLACED STOCK ASSY.	21072	\$14.00	1 150715
KY	710	71020889	06-01	WOULD NOT HOLD FIRING PIN IN.	REPLACED BOLT BODY.	21072	\$14.00	1 150535
KY	710	71021884	06-01	TRIGGER GUARD BROKEN, TRIGGER BENT.	REPLACED TRIGGER GUARD & TRIGGER.	21072	\$14.00	4 150548
WI	710	71020063	06-01	M33	REPLACED WITH STORE STOCK. RETURNED TO REMINGTON FOR EXCHANGE.	20616	\$14.00	9 152326
WI	710	71022203	06-01	TRIGGER GUARD BROKEN.	REMOUNTED SCOPE MOUNTS AND BORESIGHTED SCOPE.	20616	\$19.61	35 153113
WI	710	71022124	06-01	M1		20616	\$19.00	1 124239
NC	710	71021806	06-01	M21	RETURNED TO FACTORY. ADJUSTED BOLT STOP & RETAINER, CHECKED OUT.	21102	\$25.00	11 123008
TX	710	71021042	06-01	BOLT FALLS OUT.		21017	\$17.50	5 59927
KY	710	71018511	06-01	BOLT STOP BROKEN.	REPLACED BOLT STOP.	21072	\$17.50	4 157561
KY	710	71019316	06-01	BOLT WILL NOT CHAMBER ON ROUND.	REPLACED BOLT HEAD AND FUNCTION TESTED.	21072	\$17.50	2 157565
KY	710	71020225	06-01	BROKEN BOLT STOP.	BROKEN BOLT BOLT, ADDED BOLT SPRING.	21072	\$14.00	1 157661
KY	710	71020497	06-01	MAG RELEASE BROKEN.		21072	\$14.00	8 124080
KY	710	71019024	06-01	BOLT HANDLE BROKE.		21072	\$14.00	1 124082
KY	710	71022061	06-01	FIRING PIN ASSY COMES OUT WHEN FIRED.	REPLACED BOLT BODY AND TEST FIRED.	21072	\$19.75	4 124086
KY	710	71020512	06-01	CLOSES VERY HARD OVER SHELL.	REPLACED BOLT HEAD AND TESTED.	21072	\$14.00	1 124049

Subject to Protective Order - Williams v. Remington

BARBER - REM DOCSB0010191

MAE00010107