

KY	710	71020837	06-01	BOLT IS NOT SMOOTH.	REPLACED BODY.	21072	\$14.00	8 150800
KY	710	71019573	06-01	WON'T FIRE.	REPLACED FIRING PIN ASSY & BOLT.	21072	\$16.25	23 150591
KY	710	71023481	07-01	MAG LATCH.	UPDATED.	21072	\$14.00	8 150656
KY	710	71023937	07-01	M5	BOLT BODY.	21072	\$14.00	5 150675
KY	710	71025919	07-01	M5	UPDATED.	21072	\$14.00	5 150673
KY	710	71025469	07-01	KEEPS JUMPING OFF LINE.	REPLACED SCOPE.	21072	\$14.00	3 150677
KY	710	71021493	07-01	MAG CATCH.	STOCK AND BOLT STOP SPRING.	21072	\$14.00	1 150691
KY	710	71025911	07-01	M5	UPDATED.	21072	\$14.00	1 150614
AL	710	71025470	07-01	RETURN TO PADUCAH.	RETURNED TO PADUCAH.	21056	\$8.50	6 141622
CA	710	71025333	07-01	M5	SENT TO FACTORY.	20106	\$27.52	7 149356
OH	710	71025258	07-01	30-06 BBL ON A 270 GUN.	SENT TO PADUCAH SHOOTERS SUPPLY.	21060	\$23.75	0 SH4630
KY	710	71021553	07-01	WILL NOT FIRE.	BOLT SAFETY NOT FULLY DISENGAGED AND TEST FIRED.	21072	\$16.25	1 124034
KY	710	71023797	07-01	PLASTIC CAP ON FIRING PIN ASSY BROKEN.	REPLACED PLASTIC CAP ON FIRING PIN ASSY.	21072	\$14.00	5 150747
KY	710	71023027	07-01	BOLT HEAD HAD BURRS ON IT.	REPLACED BOLT HEAD.	21072	\$14.00	7 150492
KY	710	71024579	07-01	M5	POLISHED CHAMBER AND UPDATED.	21072	\$24.00	1 150730
KY	710	71023167	07-01	MAG LATCH BROKEN.	REPLACED MAG LATCH.	21072	\$14.00	1 150722
KY	710	71025307	07-01	BOLT NOT GOING IN ALL THE WAY.	REINSTALLED RIGHT BACKER AND TESTED.	21072	\$14.00	1 150718
KY	710	71023635	07-01	MAG LATCH BROKE.	REPLACED STOCK AND ADDED BOLT STOP CLIP.	21072	\$14.00	1 150531
KY	710	71023588	07-01	FIRING PIN ASSY BROKEN.	REPLACED FIRING PIN ASSY.	21072	\$14.00	7 150481

Subject to Protective Order: Williams v. Remington

BARBER - REM DOCSB0010192

MAE00010108